





USER MANUAL RTS-820 SERIES



CONTENT

FORWORDS	1
PRECAUTIONS:	2
1. APPEARANCE AND FUNCTIONS	3
1.1 APPEARANCE	3
1.2 DISPLAY	5
1.3 KEYPAD	5
1.4 SOFT KEYS	6
1.5 SYMBOLS	7
1.6 ILLUMINATION & SOUND	8
1.7 AUTO POWER OFF	9
2. PREPARATION FOR MEASUREMENT	10
2.1 UNPACKING AND STORE OF INSTRUMENT	
2.2 INSTRUMENT SETUP	10
2.3 BATTERY POWER REMAINING DISPLAY	12
2.4 REFLECTOR PRISMS	
2.5 MOUNTING AND DISMOUNTING INSTRUMENT FROM TRIBRACH	
2.6 EYEPIECE ADJUSTMENT AND COLLIMATING OBJECT	
2.7 INPUTTING MODE	
2.7.1 Input Characters	
2.7.2 Edit Characters	
2.8 METHOD TO INPUT PTID	
2.8.1 Enter an Existing Point	
2.8.2 Enter a New Point	
2.8.3 Search Via Wildcard "*"	
2.8.4 Enter a Point from the Point List	
2.8.5 Enter a Point from the Stack	
2.8.6 Press [REC/ENT] without a Point Name	
2.8.7 Record an Instant Measurement	
2.9 LEVELING	
3 ROUTINE MEASUREMENTS	24
3.1 CAUTIONS FOR DISTANCE MEASUREMENT:	24
3.2 EDM SETTING	
3.3 HOT KEY	25
3.3.1 Set the Height of the Target	25
3.3.2 Set the Temperature & Pressure	26

	3.3.3 Select Target Set	27
	3.3.4 Enter a Field Note	28
	3.4 START SURVEY	28
	3.5 ANGLE MEASUREMENT	30
	3.5.1 OSET 30	
	3.5.2 Enter the Horizontal Angle	31
	3.5.3 Repeat Angle Measurement	31
	3.5.4 Face-1/Face 2 Measurement	33
	3.5.5 Hold 34	
	3.6 QUICK CODES	34
4.	T ABC KEY	37
	4.1 SET UP A STATION WITH KNOWN POINTS	37
	4.1.1 Set up a Station with Known Coordinates	37
	4.1.2 Sight the Backsight by Entering the Azimuth Angle	
	4.2 MULTIPLE POINT RESECTION	
	4.3 QUICK STATION	46
	4.4 HEIGHT TRANSFER (DETERMINING STATION ELEVATION)	
	4.5 CHECKING AND RESETTING THE BACKSIGHT DIRECTION	
5.	S-O DEF KEY	51
	5.1 STAKE OUT ANGLE AND DISTANCE	
	5.2 COORDINATES STAKEOUT	
	5.3 PARTLINE SO	
	5.4 REFLINE STAKEOUT	
	o/s вні	
6.	KEY	63
	6.1 DISTANCE OFFSETS	63
	6.2 MEASURING ANGLE OFFSETS	64
	6.3 TWO-PRISM POLE	66
	6.4 +HA LINE	67
	6.5 INPUT HD	68
	6.6 CALCULATE A CORNER POINT	69
	6.7 COLUMN	70
	6.8 EXTEND THE SLOPE DISTANCE	71
7.	PRGJKL 4 KEY	73
	7.1 2 POINT REFLINE	
	7.2 REFERENCE ARC	
	7.3 REMOTE DISTANCE MEASUREMENT	
	7.3.1 MimRadial	
	7.3.2 Mim Cont	

	7.4 REMOTE ELEVATION MEASUREMENT (REM)	80
	7.5 2-PT REFERENCE PLANE (V-PLANE)	82
	7.6 3-PT REFERENCE PLANE (S-PLANE)	83
	7.7 ROADS	85
	7.7.1 Define HZ Alignment	85
	7.7.2 Edit Horizontal Alignment Data	90
	7.7.3 Receive HZ AL	91
	7.7.4 Delete Horizontal Alignment Data	92
	7.7.5 Define Vertical Alignment	93
	7.7.6 Edit Vertical Alignment Data	94
	7.7.7 Delete Vertical Alignment Data	94
	7.7.8 Stn Setup	95
	7.7.9 Stake out Roads	96
	7.7.10 Slope Stake-out	100
0	CODMNO	102
8.	KEY	103
9.	DAT PQR 6 ■ KEY	105
٦.		
10). USR1 STU / USR2 www KEY	106
11	L. MENU KEY	108
	11.1 JOB	108
	11.1.1 Open a Job	
	11.1.2 Create a New Job	
	11.1.3 Delete Jobs	
	11.1.4 Set the Control Job	
	11.1.5 Display Job Information	
	11.2 COORDINATE GEOMETRY (COGO) CALCULATIONS	
	11.2.1 Inverse Calculating	
	11.2.1.1 Inverse PT-PT	
	11.2.1.2 3PT Angle	114
	11.2.2 Azimuth and Distance (AZ&Dist)	
	11.2.2.1 AZ+HD	
	11.2.2.2 Store	116
	11.2.3 Calculate Area	117
	11.2.4 Line and Offset	
	11.2.5 Input Coordinates Manually	
	11.3 SETTINGS	
	11.4 VIEW RECORDS	122
	11.4.1 View Raw Data	123
	11.4.1.1 ST Records	
		1⊿ 1

11.4.1.2 SO Records	
11.4.1.3 CO (code) Records	
11.4.2 Delete Raw Records	125
11.4.3 Edit Raw Records	126
11.4.4 Search Raw Records	126
11.4.5 View Coordinates Data	127
11.4.6 Delet Coordinate Records	128
11.4.7 Edit Coordinate Data	129
11.4.8 Search Coordinate Records	130
11.4.9 Enter Coordinates	131
11.4.10 ViewRecords By Station	131
11.4.11 Delete Station Records	132
11.4.12 Edit Station Records	133
11.4.13 Search Station Records	134
11.4.14 Point Name List and Code List	134
11.4.14.1 Delete Points/Codes	135
11.4.14.2 Edit Points/Codes	135
11.4.14.3 Add a Point Name	136
11.4.14.4 Add a Code	136
11.5 COMMUNICATION	137
11.5.1 Download Data	137
11.5.2 Upload the Coordinate Data	141
11.5.3 Upload a PT List or Code List	144
11.6 1 SEC-KEYS	145
11.6.1 [Meas] Key Setting	145
11.6.2 [DISP] Key Settings	146
11.6.3 [User] Key Settings	146
11.6.4 [SO] Key Settings	147
11.6.5 [Data] Key Settings	148
11.7 DATE AND TIME	148
11.8 FORMAT	149
11.9 INFORMATION	149
12. CHECK AND ADJUSTMENT	150
·	
12.1 PLATE VIAL	150
12.2 CIRCULAR VIAL	150
12.3 INCLINATION OF RETICLE	
12.4 PERPENDICULARITY BETWEEN LINE OF SIGHT AND HORIZONTAL AXIS (2C)	152
12.5 VERTICAL INDEX DIFFERENCE COMPENSATION	153
$12.6\text{adjustment of vertical index difference (I \text{angle})}\&\text{setting vertical index}\text{o}$	154
12.7 OPTICAL PLUMMET	155
12.8 INSTRUMENT CONSTANT (K)	156

	PARALLEL BETWEEN LINE OF SIGHT AND EMITTING PHOTOELECTRIC AXIS	157
12.	LO TRIBRACH LEVELING SCREW	158
12.	11 RELATED PARTS FOR REFLECTOR	158
13. SI	PECIFICATION	159
14. E	RROR CODE LIST	162
15. SA	AFETY GUIDE	163
15.3	I INTEGRATED DISTANCE METER (VISIBLE LASER)	163
	2 LASER PLUMMET	
16. A	CCESSORIES	165
(AP	PENDIX-A DESIGN ROAD LINE DATA	166
(AP)		
	RAW DATA	166
1.		166 167
1. 2.	RAW DATACOORDINATE DATACODE LISTHORIZONTAL LINE	166 167 167
1. 2. 3.	RAW DATACOORDINATE DATACODE LIST	166 167 167
1. 2. 3. 4. 5.	RAW DATACOORDINATE DATACODE LISTHORIZONTAL LINE	166 167 168 169
1. 2. 3. 4. 5.	RAW DATA COORDINATE DATA CODE LIST HORIZONTAL LINE VERTICAL CURVE	166167168169170



FORWORDS

Thank you very much for purchasing the Ruide Total Station RTS-820 series! This manual will give a detailed and complete instruction about this new type total station. Please read it carefully before using the instrument.



PRECAUTIONS:


- 1. Do not collimate the objective lens directly to the sunlight without a filter.
- 2. Do not store the instrument in extremely high or low temperature, inorder to avoid the sudden or great change of temperature.
- 3. When the instrument is not in use, store it in the case and avoid shock, dust and humidity.
- 4. If there is great difference between the temperature in work site and that in store place, you should leave the instrument in the case till it adapts to the temperature of environment.
- 5. If the instrument has not been used for a long time, you should remove the battery for separate storage. The battery should be charged once a month.
- 6. When transporting the instrument should be placed in its carrying case, it is recommended that cushioned material should be used around the case for support.
- 7. For less vibration and better accuracy, the instrument should be set up on a wooden tripod rather than an aluminum tripod.
 - 8. Clean exposed optical parts with degreased cotton or less tissue only!
- 9. Clean the instrument surface with a woolen cloth after use. If it gets wet, dry it immediately.
- 10. Before opening, inspect the power, functions and indications of the instrument as well as its initial setting and correction parameters.
- 11. Unless the user is a maintenance specialist, do not attempt to disassemble the instrument by yourself even if you find the instrument abnormal.



1. APPEARANCE AND FUNCTIONS


1.1 APPEARANCE








1.2 DISPLAY



Basic Measurement Menu

- Confirm the battery power shown on the display. Replace it with another charged battery or change it when battery level is low. Refer to section 2.3 "Battery Power Remaining Display".
- The chart above is the display screen. It is possible that local software versions are different from the basic version.

1.3 KEYPAD





1.4 SOFT KEYS

Key	Function					
PWR	Power ON/OFF					
*	Illumination ON/OFF					
MENU	Displays the Function Menu 1. Job 2. Cogo 3. Set 4. Data 5. Comm 6. 1 Sec. 7. Adjust 8. Time 9. Format 10. Info					
MODE	Changes the mode of input: alphabetic/numeric; launches quick code mode in basic measurement screen.					
REC /ENI	Accepts the input or record the data; In basic measurement screen, press it for 1 second to select the data saving mode (CP or SS).					
ESC	Returns to last screen; cancels the data input.					
MSR 1	Measures the distance according to the measurement mode this key has been set. Press it for 1 second to view and change the measurement mode.					
MSR2	Measures the distance according to the measurement mode this key has been set. Press it for 1 second to view and change the measurement mode.					
DSP	Key of shifting the screen; e.g. press this key to shift the screen. Press it for 1 second to launch customizing items.					
ANG	Displays the angle measuring menu; sets the horizontal angle to zero; Continuous angle measuring; F1/F2 angle measuring; maintains the horizontal angle.					
STN ABC	Displays the Station Setup menu; inputs the number 7, letter A, B, and C.					
S-O DEF	Displays the stake-out menu, press it for 1 second to display the setting about stake-out; inputs number 8, and letter D, E, F.					
o/s GHI	Displays the Offset Point Measurement menu; inputs number 9, letter G,H,I.					
PRG JKL	Displays the Programs menu; inputs number 4, letter J, K, L.					
COD MNO	Opens a window where you can enter a code. The default code value is the last code entered. Inputs number 5, and letter M, N, O.					



DAT POR	Displays RAW, XYZ, or STN data, depending on your setting.
6	Inputs number 6, and letter P, Q, R.
USR1 STU	Executes the function that is assigned to the User Key. Inputs
1	number 1, and letter S, T, U.
USR 2	Executes the function that is assigned to the User Key. Inputs
2	number 2, and letter V, W, X.
3 Y Z	Inputs number 3, letter Y, Z, and Space.
HOT -+	Displays the (Hot) menu. Inputs – and +.
*/= 0 •	Displays the electric bubble indicator; inputs * , $/$, =, and 0.

1.5 SYMBOLS

According to different software versions, the symbols indicate specific working status.

Key	Meaning		
◀, ▶	Please select via left/right key.		
▲, ▼	To display each screen via up/down key.		
↓ , ↑	Indicates that several pages are selectable. Press it to turn the page.		
F1, F2	Indicates that the telescope (alidade) is on Face1 or Face 2. F1 Face 1 Measurement: the raster disc is on the left of telescope when measuring. F2 Face 2 Measurement: the raster disc is on the right of telescope when measuring.		


Symbols Displayed on the Screen

HA	horizontal angle
VA	vertical angle
SD	slide distance
AZ	azimuth angle
HD	horizontal distance
VD	vertical distance
HL	Horizontal angle (left): 360°-HA
V%	ratio of slope
N	North coordinate
Е	East coordinate



Z	Elevation coordinate		
PT	point		
HT	height		
CD	code		
PPM	atmospheric coorection value		
P1	Point 1		
P2	Point 2		
HI	insrtrument height		
BS	backsight point		
ST	surveying station		
	1. A "#" behind those symbols means the automatic tilt		
	correct isn't activated.		
	2. When a "d" displays in front of those symbols, it means it		
	is a difference value.		

1.6 ILLUMINATION & SOUND



Press the illumination key ($\stackrel{\raisebox{.5cm}{\rightleftharpoons}}{\blacksquare}$) to turn the LCD backlight ON and OFF.

Press illumination key for 1 second to open a 3-switch window described above. Use the 3-switch window to adjust lighting, sound setting and contrast of the screen.

In the window opened as above, press [\blacktriangle], [\blacktriangledown] (or press [1], [2], [3], [4], [5] corresponding to the items) to choose the settings for switch. When an item is selected, the function corresponding to the key can be launched ON/OFF by pressing the corresponding number.

STEP	OPERATION	DISPLAY	
① Press for 1 second to open the window of setting LCD light, sound, contrast, laser plummet and	- \$	Display HA# 30°21′50″ VA# 273°13′42″ SD#	1 ⊕; 2 ⊕ ∈ 3 ↔ 1 4 ↓
laser pointer.		PT: RUIDE HT: 1.000 m	5 ⊶



② When the current cursor is on the item of LCD light, press [1] to switch off the light; press again to switch it on. CD backlight ON LCD backlight OFF	[1]	Display HA# 30°21′50″ VA# 273°13′42″ SD# PT:RUIDE HT: 1.000 m	1 ♀ 2 ᠿ 3 ↔ 14 ↓ 5 ∘ □
③ Press [2] or [▼] to move to sound item. Press 2 to switch the sound ON/OFF.	[2] or [▼] + [2]	Display HA# 30°21′50″ VA# 273°13′42″ SD# PT: RUIDE HT: 1.000 m	1 ♀ 2 ♠ 3 ↔ m 4 ₺ 5 ⊶
④ Press [3] or [▼] to move to contrast item. Press [3] continuously to adjust the contrast level.	[3] or [▼] + [3]	Display HA# 30°21′50″ VA# 273°13′42″ SD# PT: RUIDE HT: 1.000 m	1 ♀ 2 € € € € € € € € € € € € € € € € € €
⑤Press [4] or [▼] to move to laser pointer item. Press [4] to turn on or off the laser pointer. ※1	[4] or [▼] + [4]	Display HA# 30°21′50″ VA# 273°13′42″ SD# PT: RUIDE HT: 1.000 m	1 ⊕ 2 ⊕ 3 ↔ n
⑥Press [5] or [▼] to move to laser laser plummet item. Press [5] to turn on or off the laser plummet. ※2 ※1, ※2 Laser pointer and laser plum	[5] or [▼] + [5]	Display HA# 30°21′50″ VA# 273°13′42″ SD# PT: RUIDE HT: 1.000 m	1

1.7 AUTO POWER OFF

The system-default time of Auto Power OFF is 30 minutes. If no key is pressed within this time, the instrument will be switched off in order to save the battery.



2. PREPARATION FOR MEASUREMENT

2.1 UNPACKING AND STORE OF INSTRUMENT

Unpacking

Place the case lightly with the cover upward, and unlock the case, take out the instrument.

· Store of instrument

Cover the telescope cap, place the instrument into the case with the vertical clamp screw and circular vial upwards (Objective lens towards tribrach), and slightly tighten the vertical clamp screw and lock the case.

2.2 INSTRUMENT SETUP


Mount the instrument to the tripod. Level and center the instrument precisely to ensure the best performance.

Operation Reference:

- 1. Leveling and Centering the Instrument by plumb bob
 - 1) Setting up the tripod
 - ① First, extend the extension legs to suitable length, make the tripod head parallel to the ground and tighten the screws.
 - ② Make the centre of the tripod and the occupied point approximately on the same plumb line.
 - ③ Step on the tripod to make sure if it is well stationed on the ground.
 - 2) Attaching the instrument on the tripod

Place the instrument carefully on the tripod head and slide the instrument by loosening the tripod screw. If the plumb bob is positioned right over the center of the point, slightly tighten the tripod.

- 3) Roughly leveling the instrument by using the circular vial
 - ① Turn the leveling screw A and B to move the bubble in the circular vial, in which case the bubble is located on a line perpendicular to a line running through the centers of the two leveling screw being adjusted.







2) Turn the leveling screw C to move the bubble to the center of the circular vial.



- 4) Precisely leveling by using the plate vial
 - ① Rotate the instrument horizontally by loosening the Horizontal Clamp Screw and place the plate vial parallel to the line connecting leveling screw A and B, and then bring the bubble to the center of the plate vial by turning the leveling screws A and B.



2 Rotate the instrument 90 (100g) around its vertical axis and turn the remaining leveling screw or leveling C to center the bubble once more.



- ③Repeat the steps ①② for each 90 (100g) rotation of the instrument and check whether the bubble is correctly centered in all directions.
- 2. Centering by using the optical plummet
 - 1) Set tripod

Lift tripod to suitable height, ensure equal length of three legs, spread and make tripod head parallel to the ground, and place it right above the measurement station point. Prop up tripod on the ground and fix one leg.

2) Install instrument and collimate the point

Set instrument carefully on tripod, tighten the central connecting screw and adjust optical plummet to make the reticle distinctly. Hold the other two unfixed



legs with both hands and adjust position of these two legs through observation of optical plummet. As it approximately aims at the station point, make all three legs fixed on the ground. Adjust three leg screws of the instrument to make optical plummet collimate precisely to the station point.

3) Use circular vial to roughly level the instrument.

Adjust length of three legs of tripod; make the circular vial bubble of the instrument in the middle.


- 4) Use plate vial to level the instrument accurately.
 - ①Rotate the instrument horizontally by loosening the Horizontal Clamp Screw and place the plate vial parallel to the line connecting leveling screw A and B, and then bring the bubble to the center of the plate vial by turning the leveling screws A and B.
 - ②Rotate the instrument 90°C, make it perpendicular to the connecting line of level screws A and B. Turn level screw C to make the bubble of the plate vial in the middle.
- 5) Precisely centering and leveling


Through observation of optical plummet, slightly loosen the central connecting screw and move the instrument evenly (Don't rotate the instrument), making the instrument precisely collimating to the station point. Then tighten the central connecting screw and level the instrument precisely again.

Repeat this operation till the instrument collimate precisely to the measurement station point.

2.3 BATTERY POWER REMAINING DISPLAY

Battery power remaining display indicates the power condition.





Note:

1) The battery operating time will vary depending on the environmental conditions



such as ambient temperature, charging time, the number of times of charging and discharging etc. It is recommended for safety to charge the battery beforehand or to prepare spare full charged batteries.

- ② The battery power remaining display shows the power level regarding the current measurement mode. The distance measurement mode consumes more power than angle measurement mode, so the power enough for the latter is not sure applicable for the previous one. Pay particular attention to this when switching angle measurement mode to distance measurement mode, because insufficient battery power might lead to interrupted operation.
- Before outdoor operation, battery power status should be well checked.
- ③ When the measurement mode is changed, the battery power would not immediately show the decrease or increase. The battery power indicating system shows the general status but not the instantaneous change of battery power.

Battery Recharging Cautions:

 $\stackrel{\star}{\simeq}$ Battery should be recharged only with the charger SC-21 going with the instrument.

Remove the on-board battery from instrument and connect it to battery charger. When the indicator lamp on the battery charger is orange, the recharging process has begun. When charging is complete (indicator lamp turns green), disconnect the charger from its power source.

Battery Removal Cautions

Before removing the battery from the instrument, make sure that the power is turned off. Otherwise, the instrument may be damaged.

Battery Recharging Cautions

The charger has built-in circuitry for protection from overcharging. However, do not leave the charger plugged into the power outlet after recharging is completed.

Be sure to recharge the battery at a temperature of 0° $\pm 45^{\circ}$ C, recharging may be abnormal beyond the specified temperature range .

When the indicator lamp does not light after connecting the battery and charger, either the battery or the charger may be damaged. Please connect professionals for repairing.

Battery Charging Cautions

Rechargeable battery can be repeatedly recharged 300 to 500 times. Complete discharge of the battery may shorten its service life.

In order to get the maximum service life, be sure to recharge it at least once a month.




2.4 REFLECTOR PRISMS

When measuring distance, a reflector prism needs to be placed at the target place. Reflector systems come with single prism and triple prisms, which can be mounted with tribrach onto a tripod or mounted onto a prism pole. Reflector systems can be self-configured by users according to the job.

2.5 MOUNTING AND DISMOUNTING INSTRUMENT FROM TRIBRACH

Dismounting

If necessary, the instrument (including reflector prisms with the same tribrach) can be dismounted from tribrach. Loosen the tribrach locking screw in the locking knob with a screwdriver. Turn the locking knob about 180° counter-clockwise to disengage anchor jaws, and take off the instrument from tribrach.



Mounting

Insert three anchor jaws into holes in tribrach and line up the directing stub with the directing slot. Turn the locking knob about 180°clockwise and tighten the locking screw with a screwdriver.

2.6 EYEPIECE ADJUSTMENT AND COLLIMATING OBJECT

Method of Collimating Object (for reference)

- ① Sight the Telescope to bright place and rotate the eyepiece tube to make the reticle clear.
 - ② Collimate the target point with top of the triangle mark in the coarse collimator.



(Keep a certain distance between eye and the coarse collimator).

③ Make the target image clear with the telescope focusing screw.

☆ If there is parallax when your eye moves up, down or left, right, it means the diopter of eyepiece lens or focus is not well adjusted and accuracy will be influenced, so you should adjust the eyepiece tube carefully to eliminate the parallax.

2.7 INPUTTING MODE

All characters can be input in the screen.

Press [◀] to delete one character in the left of the cursor.

When the inputting scale is wider than the screen, it can be moved to left automatically. When the inputting scale is full, it cannot be input anymore.

When an A is displayed on the upper right corner of the screen, letters can be input via the keypad. While 1 is displayed, numbers can be input. In any measurment screens or screens that need to be input manually, press [MODE] to shift between alphabet mode and numeric mode.

In letter inputting mode, 3 letters are set in one key. Every pressing can display one of the letters in the cursor.

2.7.1 Input Characters

STEP	OPERATION	DISPLAY
①Make sure that the current inputting mode is alphabet mode. If not, press [MODE].		Input STN
②Press [6] 3 times to input R.	[6]	Input STN
Press [1] 3 times to input U.	[1]	ST: RUIDE A
Press [9] 3 times to input I. Press	[9]	HI: 1.000 m
[8] once to input D.	[8]	CD: RUIDE
Press [8] twice to input E.	[8]	List Stac
③Press [MODE] to shift the inputting mode to number inputting.	[MODE]	Input STN ST: RUIDE800 1 HI: 1,000 m CD: RUIDE List Stace Stac



④Press [8] and [0]. ※1)	[8] [0]	Input STN ST: RUIDE800 1 HI: 1,000 m CD: RUIDE List Stace St	
⑤After inputting, press [REC/ENT] to confirm.※2)	[REC/ENT]		
※1) The maximum length of characte	er of point ID or p	point number is 16.	
※2) If the point ID is wrong, press [ES	C] and input ag	ain.	

2.7.2 Edit Characters

Characters that have been input can be edited.

STEP	OPERATION	DISPLAY
① Move the cursor to the item that needs to be edited, and press [▶], the cursor will stay on the first character and twinkle.	[▶]	Input STN ST: RUIDE800 A HI: 1.000 m CD: RUIDE List Stac
②Press [▶] to move the cursor to the character that needs to be edited. ※1)	[▶]	Input STN ST: RUIDE800 A HI: 1.000 m CD: RUIDE List Stac
③Input new character.	New character	Input STN ST: RUIDE820 A HI: 1.000 m CD: RUIDE
		List Stac
④Press [REC/ENT] to confirm. The cursor moves to next item.	[REC/ENT]	List Stac

2.8 METHOD TO INPUT PTID

Basically, the default name for a new point is the last point name entered, with the last digit incremented. When the last character of the previous point name is



alphabetic, it is named by adding 1 to the end of the last letter. When the cursor is in the PT field, there are several ways to specify a point or input coordinates. Here, take station PtID for example.

2.8.1 Enter an Existing Point

STEP	OPERATION	DISPLAY
① Input PtID in PT item and press [REC/ENT].	[REC/ENT]	Input STN ST:
②The system automatically searches the PtID in internal memory. When this PtID exists, its coordinate will be displayed on the screen.		N: 10.000 m E: 10.000 m Z: 10.000 m PT: AD1 CD: RUIDE
③ Press [REC/ENT] to return to the screen. The point is called up. The cursor moves to next item.	[REC/ENT]	Input STN

2.8.2 Enter a New Point

STEP	OPERATION	DISPLAY
① Input PtID in PT item and press [REC/ENT].	[REC/ENT]	Input STN ST: 1 HI: 1,000 m CD: RUIDE In
② When you input a new point name or number, a coordinate input screen appears. Enter the coordinate. After inputting one item, press [REC/ENT] to move to next	Input coordinated +	N:
item.	[REC/ENT]	



② After inputting coordinate data, input the code (if necessary) in the last row (CD item). Press [REC/ENT] to store this point to current project.	Input CD + [REC/ENT]	N: 10,000 m E: 10,000 m Z: 10,000 m PT: 2 CD: List Stac
③Return. The cursor moves to next item.		Input STN 1 1 1

2.8.3 Search Via Wildcard "*"

Wildcard "*" can be represented a character that needs to be found.

The function of searching via wildcard is useful when the point ID that needs to be searched is unknown, or a series of points needs to be found.

e.g.:

- * All points of any length are found.
- A All points with exactly the pointID "A" are found.
- A* All points of any length starting with "A" are found (e.g.: A8, A71, ABDE)
- *1 All points of any length with a "1" as the second character are found (e.g.: W1, F15, A1R)

A*1 All points of any length with an "A" as the first character and a "1" as the third character are found. (e.g.: AD1, AR100, AS16)

STEP	OPERATION	DISPLAY
①In PT item, insert wildcard "*" (Here take "*" for example), and press [REC/ENT]	Input [*] + [REC/ENT]	Input STN ST: * A HI: 1.000 m CD: RUIDE List Stac
②Press up/down and [REC/ENT] to select the point. When [▲] or [▼] appears in the list, left/right can turn the page.	[▲]/[▼] + [REC/ENT]	MP,1,RUIDE MP,2, CODE CP.4, 870 CP.5 CP,6 SS,7,5841 ▼
3When a point is select from the list, the coordinate will be displayed on the screen.		N: 10.000 m E: 10.000 m Z: 10.000 m PT: 2 CD:



Press [REC/ENT] to return. This point is called up. The cursor moves to next item.	Input STN 1 1 1
	List Stac

2.8.4 Enter a Point from the Point List

Point ID can be input via [List]. The meaning of the PtID list is the same as that of code list.

STEP	OPERATION	DISPLAY
①Press [List] softkey when the cursor is in the PT field.	[List]	Input STN
②PtID list is displayed. Press up/down arrowhead to move the cursor to the point that you want to use, and then press [REC/ENT].	[▲]/[▼] + [REC/ENT]	1 1145 1204 1205 230 40 ▼
③When you return to the PT input screen, the selected PtID is entered in the PT field. (You can add digits or alphabetic characters if required.) Press [REC/ENT] to confirm.		Input PT01 PT:
A: If the inputted PtID exists in internal memory, its coordinate will be displayed on the screen. Press [REC/ENT] to return.		A: N:
B: If the inputted PtID does not exist, it is required to input coordinate (as shown on the right). Input the coordinate and press [REC/ENT] to move the cursor to the code item. Input the code, press [REC/ENT] to save and quit.		B: N:



⑤Return to PT inputting screen. The cursor moves to next item.	Input PT01 PT:
--	------------------

2.8.5 Enter a Point from the Stack

STEP	OPERATION	DISPLAY
①When the cursor is on PT field, press [Stac].	[Stac]	Input STN ST:1 HI:1,000 m CD: RUIDE List Stac
②The stacks of the points are displayed. Press [▲]/ [▼] to select the PtID, and press [REC/ENT]. ③When you return to the PT input	[▲]/[▼] + [REC/ENT]	Input PT01
screen, the selected point name is entered in the PT field, incremented by one. (As shown in the right. If BC is selected, BC1 appears in the PT field; If A098 is selected, A099 appears.) Press [REC/ENT].		PT: BC1 1 HT: 1.000 m CD: List Stac
A: If the PtID exists in internal memory, its coordinate will be displayed on the screen. Press [REC/ENT] to return.		A: N:
B: If the inputted PtID does not exist, it is required to input coordinate (as shown on the right). Input the coordinate and press [REC/ENT] to move the cursor to the code item. Input the code, press [REC/ENT] to save and quit.		N:



⑤ Return to PT inputting screen. Move the cursor to next item.	Input PT01
---	------------

The stack shows the last 20 point names used, in chronological order from last used to first used. Stacks with the same type are covered.

2.8.6 Press [REC/ENT] without a Point Name

In some occasions of inputting PtID, a temporary coordinate that needn't to be saved can be used. The input coordinates are used in calculation. They are not saved in the database.

STEP	OPERATION	DISPLAY
① In PT item, press [ENT] directly without inputting its PtID.	[ENT]	Input PT01
② A coordinate inputting screen is displayed. Input the coordinate. After inputting one item, press [REC/ENT] to move to next item.	Input coordinate + [ENT]	N: E: Z: *This Pt. not save
③ After inputting, press [REC/ENT] to return.	[ENT]	Input PT01 PT:

2.8.7 Record an Instant Measurement

You can also input a point by recording an instant measurement. To do this, press the Meas softkey.

STEP	OPERATION	DISPL	AY	
① Press [Meas] in PT inputting screen.	[Meas]	Input P1 P1: P2:		1
		Meas	List	fi Stac



②An observation screen appears. Press [MSR1]/[MSR2] to start a measurement. To change the height of the target, press [Hot].	[MSR1]/ [MSR2]	HA# 32°05′34″ VA# 22°26′25″ SD# HT: 0.000 m *Sight Press [MSR]
③ After measuring, the system automatically enters into the point recording screen. Input PtID and CD, and press [REC/ENT] to record the result.	Input PT & CD	N: 10,000 m E: 10,000 m Z: 5,000 m PT: 1 CD: List Stac
④ The screen returns. The cursor moves to next item.		Input P1 P1: <coordinate measured=""> 1 P2: Meas List Stac</coordinate>

If there's alignment data in internal memory, PtID can be input via chainage number. Please refer to "7.7.8 Setting Station".

The method to input code can be input manually, called up from list and stack. The operational method is same as that of PtID inputting.

2.9 LEVELING

As the tilt sensor is activated, automatic correction of vertical angle for mislevelment is displayed.

To ensure a precise angle measurement, tilt sensor must be activated. The display can be used to fine level the instrument.

If the instrument hasn't been leveled roughly, the screen displays that the instrument is out of the automatic correction range, and that it needs to be leveled manually. Please refer to "2.2 Instrument Setup" for detailed leveling instruction.

RUIDE Total Station RTS-820 Series compensates the vertical angle reading as well as both vertical and horizontal angle reading due to inclination of the vertical axis in the X direction and XY directions. (Dual axis compensation is just applicable for RTS-820R³ series.

STEP	OPERATION	DISPLAY
Press to enter into automatic compensation function. ※1)	*/= 0 =	Tilt: X X: -0°50′21″ Y: Over X OFF



_	1	
② Tilt compensation value is		Tilt: X
displayed.		3 7 000010111
If the value is within ±5', it indicates		X: -0°00′21″ Y: Over
that it is in the automatic		
compensation range of the raster		X OFF
disc. Press [ESC] to return to		
measurement function. If it is		
beyond ±5', it means that it needs to		
be leveled manually.		
be leveled mandally.		
		Tilt: XY
③ Press MSR2 to shift the		X: -0°00′21″
compensation mode to dual axis		Y: -0 00 21 Y: -0 03'44"
compensation. ※2)		XY OFF
·		
③ After leveling, press [ESC] to		
return to previous status.		
※1) To close automatic compensation		
※2) Dual axis compensation mode is	just applicable	for RTS-820R ³ series.

When the instrument is placed on an unstable stage or in a windy weather condition, the display of vertical angle is unstable. You can switch off the auto tilt correction function of vertical angle.

If the mode of auto correction is ON, in the condition that the instrument has not been leveled, the program will demand that the instrument must be leveled at first, so as to enter other functions.




3 ROUTINE MEASUREMENTS

3.1 CAUTIONS FOR DISTANCE MEASUREMENT:

After setting up and switching on correctly, the Total Station is immediately ready for measuring.

All shown displays are examples. It is possible that local software versions are different from the basic one.

Example of a possible measuring display:



3.2 EDM SETTING

Press [MSR1] or [MSR2] for 1 second to enter each measurement function it is specified.

STEP	OPERATION	DISPL	AY
①To view the measurement setting, hold down [MSR1] or [MSR2] for one second. Here take measurement mode setting in basic measurement as example.		Display AZ# HD# SD# PT: 1 HT: 1.000 n	1/5 280°56′10″ 46°29′06″
② Take the measurement mode specified on [MSR1] for example. Press [▲] or [▼] to move to the item that needs to be modified, and press [◀] or [▶] to change the options. ※1)	[MSR1]/ [MSR2] for 1 second.	<msr1> TGT: Prism Const: _30m Mode: Fine Rec: All</msr1>	<u>m.</u>
③ After setting, press [REC/ENT] to save the setting and return to last screen. ※2)	[REC/ENT]	Display AZ# HD# SD# PT: 1 HT: 1.000 n	1/5 280°56′10″ 46°29′06″
※1) All options in each item in measurement setting: TGT: Prism, reflector sheet and non-prism (only or reflectorless instrument). Const: Input prism constant directly (under prism mode). Scale: -999~999mm Mode: Fine[s], Fine [2] ([3]/ [4]/ [5]), Fine[r], Tracking.			



Rec: Enter, All, Meas. This mode controls the mode operation of [MSR1]/MSR2] in basic measurement function.

If "Enter" is adopted, a screen of "Rec Pt" is displayed to inform the user to check and confirm before data is recorded.

"All" is a quick shooting and recording mode. The instrument automatically records the point using the default PtID, and then returns to the basic measurement screen.

"Meas" is the default measuring mode. After a measurement, the instrument stops in the BMS and waits for you to press [REC/ENT] before recording the point.

%2) The measurement mode setting of [MSR2] is the same as it. When pressing [MSR1] or [MSR2], the system activates the corresponding measurement mode to measure.

3.3 HOT KEY

[HOT] Key includes the inputting function of target height, temperature & pressure, target selection and note. It is available on any observation screen.

3.3.1 Set the Height of the Target

To change the height of the target (HT) or temperature, pressure, press [HOT].

STEP	OPERATION	DISPLAY
① Press [HOT] to display the [HOT] key menu.	[HOT]	1. Input HT 2. Temp&Pres 3. TGT 4. Note
② Press [1] to enter into HT setting function.	[1]	HT: 1.000 m
③Enter the height of the target manually or press the [Stac] softkey to display the HT stack. The HT Stack stores the last 20 HT values entered. As shown in the right.	Input target height or [Stac]	Input HT HT: 1.800 m Stac 1.000 m 2.000 m 3.000 m 3.200 m 4.100 m 5.000 m



Press [REC/ENT] to return to basic measurement screen.	[REC/ENT]	Display HA# VA# SD# PT: 1	1/5 280°56′10″ 46°29′06″	
		HT:	1.000 m	

3.3.2 Set the Temperature & Pressure

Atmosphere Correction:

The speed of light in air is extremely fast. And it is not a constant, but changes with the temperature and pressure of atmosphere. Once atmosphere correction is set, this instrument can implement atmosphere correction automatically.

Even the instrument is powered off, the atmosphere correction value is still kept.

The formula of atmosphere correction: (unit: meter))

PPM = 273.8 -
$$0.2900 \times \text{pressure value (hPa)}$$

1 + 0.00366 × temperature value (°C)
If the pressure unit is mmHg:
1hPa = 0.75mmHg

When disregarding atmosphere correction, set PPM value to 0.

Standard atmospheric condition of Total Station RTS Series (i.e. the atmospheric condition that the atmosphere correction value of the instrument is 0):

Pressure: $1013 \, \text{hPa}$ Temperature: $20 \, ^{\circ}\text{C}$

Using [HOT] Key and [2] can set temperature and pressure values. Enter the ambient temperature and pressure, the PPM value is updated automatically.

STEP	OPERATION	DISPLAY
① Press [2] in HOT key menu to enter into Temp&Pres Setting.	[2]	1. Input HT 2. Temp&Pres 3. TGT 4. Note
② The screen displays the current	Input	Temp&Pres
setting values. Input temperature	temperature	Temp: 20.0 ℃
value and press [REC/ENT] to	& pressure	Press: 1013.2 hPa
move to next item. Input pressure	+	PPM=0.0
value and press [REC/ENT].※1)	[REC/ENT]	ON OFF



③ The program calculates the atmosphere correction value, and return to normal measurement screen. ※2)	Temp&Pres Temp: 20.0 °C Press: 1013.2 hPa PPM=0.0 II ON OFF		
④ Press ON to activate the automatic temperature and pressure sensor, which will detect and fill the Temp and Press automatically. ※3)	Temp&Pres Auto Temp: 28.0 °C Press: 1005.0 hPa PPM=9.6 □ ON OFF □		

Air pressure:420 \sim 799.5mmHg(step length 0.1mmHg) or 560 \sim 1066 hPa(step length 0.1hpa) 16.5 \sim 31.5 inchHg(step length 0.1 inchHg)

- ※ 2) The atmosphere correction value will be calculated by the instrument according to the inputted temperature and pressure value.
- * 3) Temp & Press Sensor is only equipped in RTS-820R³ series.

3.3.3 Select Target Set

A target set specifies settings for the target type, the prism constant, and height of target.

When you change the selected target set, all the three settings are changed. You can use this function to quickly switch between two types of targets, such as a reflecting sheet and a prism.

To select a target set, either press the corresponding numeric key (from 1 to 5), or use $[\blacktriangle]/[\blacktriangledown]$ to highlight the target set in the list and press [ENT]. To change the settings defined in a target set, highlight the target set in the list. Then press "Edit" softkey.

•When a target set is selected, the Type and Const values are copied to both [MSR1] and [MSR2] settings. If you have specified a value for HT, this value is also copied to the current HT.

STEP	OPERATION	DISPLAY
①In Hot Key menu, press numeric key [3] to enter target function.	[3]	



②Press [▲]/[▼] or numeric keys [1]~[5] to select target set, and then press [ENT]. To edit the target set, highlight the target set and press Edit. After editing, press [ENT] ※1)	[▲] /[▼] + [Edit]	1 < N, 0, 1.000 > 2 < S, 0, 1.000 > 3 < N, 0, 1.000 > 4 < P, 0, 2.000 > 5 < N, 0, 1.000 > Edit Set Press [Edit]: TGT:	
③The system starts the set target set, and returns to BMS.		Display 1/5 HA: 280°56′10″ VA: 46°29′06″ SD: PT: 1 HT: 1.000 m	
※1)Type=prism/non prism/reflector sl	neet		
Constant=-999~999mm			
HT=-9999.999~9999.999mm			
"HT" can be left blank in the target set (input the number beyond the max instrument height), the current HT value is always applied to the measurement.			

3.3.4 Enter a Field Note

To enter a field note, press [HOT] and then press [4]. This function can be used at any time on any observation screen. Each note can be up to 50 characters. The note is stored as a CD record in the raw data.

STEP	OPERATION	DISPLAY
①In HOT Key menu press numeric key [4] to enter Note function.	[4]	
② Input note and then press [ENT]. The instrument returns to the basic measurement screen.	Input Note	Input Note 1 OK

3.4 START SURVEY

After finishing all settings, you can start surveying. The survey result is displayed in 4 pages including all data of routine survey. Press DSP to view. If the 2nd unit is set, a HD/VD/SD screen will appear.



Please set a job, station and backsight azimuth before measurement.

STEP	OPERATION	DISPLAY
①Collimate to the center of target prism, press [MSR1] or [MSR2].	[MSR1]/ [MSR2]	Display 1/4 HA# 29°44′21″ VA# 265°20′53″ SD# PT: 1 HT: 1.000 m
②While the instrument is taking a measurement, the prism constant is displayed in a small font.		Display 1/4 HA# 29°44′21″ VA# 265°20′53″ SD# <30nm> PT: 1 HT: 1.000 m
③Display the result of measurement in four pages, including all normal measure functions such as measure of angle, distance and coordinate, etc. Press [DSP] or [▲]/[▼] to view each page. *If the secondary distance unit is set, another page will display.	DSP or [▲]/[▼]	First page: Display

To change the height of the target (HT), temperature, or pressure, press [HOT].



Settings that relate to corrections (T-P, Sea level, C&R) are included in the job settings. These settings are job-specific. Changing of any item will create a new job or shut off all jobs.

The maximum capacity of RTS-850 Serial Total Station is defined by the data type. Up to 10000 data can be collected at most.

3.5 ANGLE MEASUREMENT

To open the Angle menu, press [ANG] in the basic measurement screen.

STEP	OPERATION	DISPLAY
①In BMS press [ANG] to enter angle observation function.	[ANG]	Display
②To select a command from this menu, press the corresponding number key and [ENT].		HA: 359°21′11″ 1.0SET 4.F1/F2 2. Input 5.Hold 3. RePt.

3.5.1 OSETPress [1] to set HA as 0, and then return to basic measurement screen.

STEP	OPERATION	DISPLAY
①In Angle menu press [1] to enter into 0SET function.	[1]	HA: 359°21′11″ 1.0SET 4.F1/F2 2.Input 5.Hold 3. RePt.
② Program sets the current horizontal angle as 0, and returns to basic measurement screen.		Display 1/5 HA# 0°00′00″ VA# 87°04′21″ SD# m PT: RUIDE HT: 1.000 m



3.5.2 Enter the Horizontal Angle

[2]	
Input HA + [ENT]	HA Input HA: 20°00′00″ *Input HA Press [ENT]
DE.	Display 1/5 HA# 20°00′00″ VA# 87°04′21″ SD# m PT: RUIDE HT: 1.000 m
	Input HA +

3.5.3 Repeat Angle Measurement

This program is used to accumulate repeated angle measurement, displaying the sum of and average value of all observed angles. It records the observation times at the same time.

$$\mathsf{HR}\,\overline{X}\,\text{=}\!\mathsf{HR}\,\sum \div\,N$$


$$\mathsf{HA} \!\!=\!\! \mathsf{BS}\, \mathsf{A}_{\mathsf{Z}} \!+\! \mathsf{HR}\, \overline{\mathsf{X}} \; (\mathsf{normalized})$$

 $\mathsf{HR}\,\overline{X}$ is not updated even if the instrument is moved.

- ullet In repeat angle measurement, the HA is replaced by HR \sum , and the number of repeat angles is displayed (for example, N=6).
- •Horizontal angles can be measured up to 3599°59′59″.
- •This function stores both raw and XYZ data as CP records.

STEP	OPERATION	DISPLAY
①In Angle menu press [3] to enter into the repeat horizontal angle measurement function.	[3]	HA: 359°21′11″ 1.0SET 4.F1/F2 2.Input 5.Hold 3. RePt.





When you have collected enough horizontal angle results, press [MSR1] or [MSR2] to take a measurement to the foresight. The average horizontal angle is displayed. This value is fixed until the process is finished or cancelled.

STEP	OPERATION	DISPLAY
①When you have accumulated enough horizontal angles, you can take a measurement to the foresight. First sight the backsight and then press[ENT].	Sight the Backsight + [ENT]	RePt.
②Sight the foresight, press [MSR1] or [MSR2] to start surveying.	Sight the foresight + [MSR1]/ [MSR2]	RePt



		RePt.	N=03
③Display the measuring result.		HR X HA# HD: *Press [ENT] Rec Record FS Pt. as CP	46°03'48" 46°03'48" 2.335 m
④Press [ENT] to record.	[ENT]		

3.5.4 Face-1/Face 2 Measurement

Using F1/F2 measurements effectively cancels out mechanical constant error to obtain maximum accuracy for measuring angles. To take F1/F2 data without taking a distance measurement, press [ANG] \rightarrow [4] to select F1/F2 in the Angle menu.

For the HA to be adjusted from a F1/F2 measurement, the Backsight must also have been measured in F1/F2 during the station setup. $_{\circ}$

STEP	OPERATION	DISPLAY
①First sight the center of the target prism, press [MSR1]/ [MSR2] (can omit if not take a distance measurement), press [ANG] to enter into Angle menu, and then press [4] to enter F1/F2 function. ※1)	[4]	
②Program displays according to the current horizontal circle. If the horizontal circle is on F2, program displays "Turn to F1", whereas displays "Turn to F2". Here take "Turn to F1"as example. ③Rotate the alidade, and use the horizontal clamp screw and horizontal tangent to sight the same target. Press [ENT], program will calculate the observation value of F1/F2. ※2)	Sight the same target + [ENT]	*Turn to F1 ! F1/F2Obs. dHA: 0°00′00″ dVA: 15°40′00″ dSD: Abrt CP OK
④If you are satisfied with the result, press [OK], and otherwise press [Abrt]. Screen returns to BMS.	[OK] or [Abrt]	Display 1/5 HA: 20°00′00″ VA: 273°16′00″ SD: m PT: RUIDE HT: 1.000 m



**1)To measure the target, after collimating to the prism center, press [MSR1] or [MSR2].
**2) If you have already taken a distance measurement to the target, you can initiate F1/F2 averaging by flipping the telescope to the other face.

3.5.5 Hold

This seccion explains how to hold the horizontal angle reading.

To hold the horizontal angle to the current value, press [5] or select Hold in the Angle menu.

To set the horizontal angle to the displayed value, press [ENT].

To cancel the process and return to the basic measurement screen, press [ESC].

STEP	OPERATION	DISPLAY
①Press [ANG] to enter into Angle menu.	[ANG]	Angle
②Rotate the horizontal circle to needed horizontal angle, or input the needed angle value manually.		HA: 60°00′00″ 1.0SET 4.F1/F2 2.Input 5.Hold 3.RePt.
③Press [5] to enter into angle hold function. Use the horizontal clamp screw or horizontal tangent to sight the target.	[5]	#HA is hold Press [ENT]
④Press [ENT] to set the horizontal angle of the target.	[ENT]	Display

3.6 QUICK CODES

Quick codes (Qcodes) let you shoot and record many points with feature codes in the field.

Using the quick code function, a predefined code can be called up directly via numeric keypad on the instrument. The code is selected by entering a two digit number, by pressing [MSR1] the measurement is triggered and the measured data and code saved.



A total of 256 quick codes can be assigned. Each code can be assigned a unique one/ two/three digit numbers. If no numbers are allocated to the codes, the code is selected in accordance with the order in which the codes were entered in the code list (e.g.: 01->: first code in the code list. 10-> tenth code in the code list). About editing Quick Code, please refer to "11.4.14.4 Add a code"; users can also use the data transferring software provided by RUIDE to create and upload codes, please refer to "Appendix A 3: Code List".

STEP	OPERATION	DISPLAY
① In basic measurement screen, press [Mode] to enter into Quick Code function.	[MODE]	Display 1/5 HA: 60°00′00″ VA: 107°42′33″ SD: m PT: RUIDE HT: 1.000 m CD: 1/5 HA: 60°00′00″ VA: 107°42′33″ SD: m PT: 1 HT: 1.000 m
②Input the serial numbers of Quick Code, which should be Arabic numbers, and then press [ENT].	Input the serial numbers of Quick Code + [ENT]	CD: 10 1/5 HA: 60°00′00″ VA: 107°42′33″ SD: m PT: 1 HT: 1.000 m
③Program starts code searching to search the quick coding in internal memory. To find the quick coding corresponding to the code, press [MSR1], after measuring the result and Quick Code are displayed. If the quick code corresponding to the code doesn't exist in internal memory, it will display "Code no exist" ※1)		CD: 10



%1) If no quick code is allocated to the codes, the code is numbered in accordance with the order in which the codes were entered in the code list, so you can enter serial numbers to call up quick codes.

**2) To quit Quick Code function, press [MODE] again.






To open the Station Setup menu, press 7 in the BMS.

4.1 SET UP A STATION WITH KNOWN POINTS

4.1.1 Set up a Station with Known Coordinates



STEP	OPERATION	DISPLAY
		Stn Setup
①In [Stn Setup] menu press [1] to		• 1. Known
enter into the function of using	[1]	2. Rese.
	[.]	3. QuickStn
known point to set station.		(X, Y, Z) 4. Z Coord 🗓
		5. BS Check
	Input point	Input STN
②Input point name, and press	name	ST: 1 1
[ENT]. ※1)	+	HI; 0.000 m
,	[ENT]	CD:
		List Stac



③Input height of instrument (HI), then press [ENT]. To re input the known PtID, press [▲] to move to the ST item, then input the PtID.	Input height of instrument + [ENT]	Input STN 1 1 1,000 m
 Select an input method for defining the backsight point: To sight the backsight by entering coordinates. To sight the backsight by entering the azimuth and angle. 		Backsight 1. XYZ 2. Angle
※1) About method to input PtID, pleas	se refer to "2.8 ME	THOD TO INPUT PTID".

Sight the backsight by entering coordinates

About determine backsight by inputting coordinates, there are two conditions: measuring to and not measuring to the backsight point.

OPERATION DISPLAY		
STEP	OPERATION	DISPLAY
①To enter coordinates for the	[1]	Input BS PT
backsight point (BS), press [1].	+	BS:1
Enter the point name, and press	Enter point	HT: 0.000 m
[ENT]. ※1)	name	CD:
		List Stac
		Input BS PT
②There are two conditions:		BS:31
measuring and not measuring the		HT: 0.000 m
backsight point.		CD:
		Stac

1) Measure the backsight point

STEP	OPERATION	DISPLAY
③If you intend to take a distance measurement to the BS, enter the height of target in the HT field.	Enter the height of target	Input BS PT BS: 3

④Sight the BS on Face-1 (F1), press [MSR1] or [MSR 2] to record a full shot (with HAVA/SD value). ※1) If the horizontal circle is on Face-2, screen would display "Turn to F1". As show in the right graph. Rotate the telescope and alidade, and sight the BS point in Face-1.	[MSR 1]/ [MSR 2]	Stn Setup
⑤After Measuring, the result is displayed as showed in the right graph. ※2) A: To determine the backsight point only by F1, press [ENT] to end		A: Stn Setup
measuring. B1: To determine the backsight point by F2, press [F2] softkey. As showed in B1. B2: To go directly to the Face-2 measurement after taking a distance measurement to the BS on Face-1, flip the telescope. ※3) Sight the backsight point, press [MSR1] or [MSR2] to start F2 measurement, press [ENT] after measuring. If no need to measure, just press [ENT]. ※2)		B1: Stn Setup
© Press [DSP] to display a QA screen. (Quality Assessment) To record a CP record which stores the averaged HA, VA, and SD from the F1/F2 data, press the [CP] softkey. To record only the ST and F1/F2 records, without a CP record, press the [OK] softkey. Press [Abrt] to return to procedure ⑤.		Stn Setup



⑦Procedure records the station and raw data to current job and finish setting up station. Screen returns to BMS.		Display AZ# HD# SD# PT: 1 HT:	2/ 280°56′10″ 1.000 m	/5 	
※1)A7. Azimuth calculated by coordi	in at a a				_


- %2)Press [\blacktriangledown] or [DSP] to switch QA screen (dHD/dVD). dHD/dVD: indicates the difference between the measured distance and the distance calculated from the known coordinates.
- %3) The instrument automatically detects F1/F2.

2) Not measure the backsight point

STEP	OPERATION	DISPLAY
③If not measuring the backsight point, press [ENT] directly.	[ENT]	Input BS PT BS:
(4) Sight the BS point in F1, and press [ENT] to finish setting.		Stn Setup 1/2 AZ: 30°21′50″
If the horizontal circle is on Face-2,		HD: 50°21'50°
screen would display "Turn to F1".		SD: m
As show in the right graph. Rotate		* Obs.BS [MSR]/[ENT]
the telescope and alidade, and sight		F2
the BS point in Face-1.		*Turn to F1
⑤Procedure records the station and		Display 2/5
raw data to current job and finish		AZ# 280°56′10″
setting up station. Screen returns to		HD# SD#
basic measurement screen. AZ item		PT: 1
displays the result of determining		HT: 1.000 m
Backsight azimuth.		



4.1.2 Sight the Backsight by Entering the Azimuth Angle




STEP	OPERATION	DISPLAY
① To enter the azimuth angle to the backsight point, press [2] in the Backsight screen.	[2]	Backsight 1. XYZ 2. Angle
②Input a point name, and press [ENT]. Note that the backsight point here can't be known PtID in internal memory, otherwise the program will call up the coordinate of this point and enter into function of sighting the backsight by entering coordinates If only need to input azimuth, when the cursor is on BS field, press [ENT] directly.	[1] + Input point name	Input BS PT
③Enter the azimuth angle to the BS point. If you press [ENT] without entering a value in the AZ field, the azimuth is automatically set to 0°00'00".	Enter the azimuth angle to the BS point	Input Azimuth AZ:



(4)Sight the backsight point on F1	Sight BS point	Input BS PT
and press [ENT]. The screen	+	BS:1
displays as the right graph. Enter	Input height of	HT: 0.000 m
the target height of backsight point	target	CD:
and press [ENT].	+	Stac
	[ENT]	
⑤Here there are also two ways to		Stn Setup
determine backsight: measure to		AZ: 30°21′50″
and not measure to the backsight		
point.		* Obs.BS [MSR]/[ENT]
A: Not measure, press [ENT].		F2
B: measure, press [MSR1] or [MSR		
2], about detailed method please		
refer to procedure 4~6 of		
Measure to the backsight point in		*Turn to F1
Sighting the backsight by entering		Û
coordinates.		
If the horizontal circle is on Face-2,		
the screen would display "Turn to		
F1", as shown in the right graph.		
Rotate the telescope and alidade,		
and sight the backsight point in		
Face-1.		
©The system records the station		Display 1/5
and raw data to current job and		AZ# 0°00′00″
finish setting up station. The screen		
returns to basic measurement		PT: 1
screen. AZ item displays the result		HT: 1.000 m
of determining Backsight azimuth.		
	1	1



4.2 MULTIPLE POINT RESECTION



A resection sets up the station using angle/distance measurements to known points.

- --- You can use a maximum of 10 points in a resection.
- --- Measurements can be distance and angle, or angle only.
- --- Calculation starts automatically when enough measurements are taken.
- --- You can delete poor observations and recalculate if necessary.
- •If the angle between known point 1 and known point is extremely acute or extremely oblique, the resulting solution will be less reliable geometrically. For geometric reliability, select known point locations (or station point locations) that are widely spaced.

STEP	OPERATION	DISPLAY
①In [Stn Setup] menu press [2] to start the resection.	[2]	1. Known 2. Rese. 3. QuickStn 4. Z Coord 1 5. BS Check
②Enter the point name for the first observation point (PT1), and press [ENT]. ※1)	Enter the point name for the 1st observation point	Input PT01
③Enter the target height and press [ENT].	Enter the target height + [ENT]	Input PT01



④Sight the center of first target prism on F1and press [MSR1] or [MSR2] to start survey. If only need to measure angle, press [ENT]. If the horizontal circle is on Face-2, screen would display "Turn to F1". As show in the right graph. Rotate the telescope and alidade, and sight the BS point in Face-1.	Sight + [MSR1]/ [MSR2]	RESE <sight 01=""></sight>
⑤The measuring result is displayed, press [ENT]. To measure the backsight point on F2, press [F2] softkey. Rotate the telescope and alidade, and sight the center of target prism, and press [MSR1] or [MSR2]. Press [ENT] after measuring.	[ENT]	RESE <sight 01=""> </sight>
⑥If measured on F1 and F2, a QA screen appears, press [OK] or [ENT] to record the result.	[OK] or [ENT]	Stn Setup 1/2
Tenter the second point (PT2) and its height of target. Press [ENT].	Enter the second point name	Input PT02
® Repeat steps ③~⑥ to measure target point 02 and other target points.		RESE <sight 02=""> </sight>



When the instrument has enough data; it calculates the station (STN) coordinates. As shown in the right graph A. If more than 2 points are available, a standard deviation screen appears. As shown in the right graph B.		A: RESE
(10)		A:
A: To take measurements to strengthen geometry of the resection, press the [Add] softkey.	[Add]	Input PT04
B: To check the measurements to		B: View Obs. Value
each known point, press the [View] softkey. Press [▲]/[▼] to select point on the screen, and then [ENT] to check the measurements to each known point, ※2)	[View]	1, 5, 8, V Add Del
You can delete poor observations or		dHA: 0°00′10″
add observation point. ※3)		dHA: 0*00*10*/ dVD: 1.590 m dHD: 3.227 m PT: 1 HT: 1.620 m Add Del Dsp
C: Press [Dsp] to switch the dialog box of result.	[Dsp]	C: RESE



(11)Press [ENT] or [Rec.] to record the station when the results are OK, as shown in the right graph. The "ST" column defaults to the last recorded PT+1.	[ENT] or [Rec.]	Input STN 10 1
(12)BS defaults to the first observed point. To change the BS, press the [Vary] softkey. Use [▲]/[▼] to select point on the screen, and then press [ENT].	[Vary]	Input STN 10 1 HI: 1.800 m CD: BS: 1 II Vary
(13) Screen returns to Input STN menu, press [ENT] to record station and backsight. Screen returns to Stn Setup menu.	[ENT]	Input STN 10 1 1 1 1 1
 ※1) About method to input PtID, pleas ※2)dHA: Distributed HA errors in ear dVD: VD errors between measudHD: HD errors between measum ※3) To delete a measurement, highlight 	ch direction red distance and d ured distance and d	calculated distance
STN coordinates are automatically rec	calculated.	

- The minimum data required for a resection is either three angle shots, or two distance shot.
- •Basically, Stn-Z is calculated from distance-measured data. If no distances are measured, then Stn-Z is calculated using angle-only measurements to known points with 3D coordinates.

4.3 QUICK STATION

Setting up the station quickly without coordinates.

The station point (ST) in this function defaults to a new point number. For the



new point, MP (0, 0, 0) is stored as the coordinates. When the ST is manually changed to a known point name, the station is set up on the coordinates of the known point.

Even if both ST and BS are known points, this function does not calculate the backsight angle (AZ) automatically. To calculate the AZ between two known points (ST and BS), use [Stn Setup]—[1.Known].

STEP	OPERATION	DISPLAY
①In [Stn Setup] press [3] to enter into Quick Station function.	[3]	Stn Setup 1. Known 2. Rese. 3. QuickStn 4. Z Coord 1. 1. 2. 2. 3. 3. 4. 3. 4. 3. 4. 3. 4. 4
②Input the point name of ST, and press [ENT]. defaults to the last recorded PT + 1, or ST + 1, depending on the Split ST setting) ※1)	Input the point name of ST + [ENT]	QuickStn 1 ST: 1 HI: 1.800 m BS: 1 AZ: I List Stac
③Input the height of instrument, and press [ENT].	Input the instrument height + [ENT]	QuickStn 123 1 ST: 1.800 m 1.800 m BS: AZ: 1
No default PT is assigned to the BS. Leave this field blank, or enter a BS point name.		QuickStn 123 1 ST: 123 1 HI: 1.800 m BS: AZ: 1
⑤The backsight azimuth (AZ) defaults to zero, but you can change this.	Enter azimuth of BS	QuickStn ST: 123 1 HI: 1.800 m BS: AZ: II
(6)To complete the station setup, sight the BS and press [ENT].	[ENT]	

^{※1)} About the Split ST setting, please refer to "11.3 setting".


^{%2}) When you press [ENT] in the AZ field, both HA and AZ are reset to the value you have entered.



4.4 HEIGHT TRANSFER (DETERMINING STATION ELEVATION)

This function determines the height of the instrument from measurements to target points with known heights, in two faces.

After measuring, the new height of station is displayed.



STEP	OPERATION	DISPLAY
①In [Stn Setup] press [4] to enter into height transfer function.	[4]	Stn Setup
②If no station is set before, program shows the right graph.		! Invalid STN *Press any key
③Press any key to return to "Stn Setup" menu, select one method to set station.		1. Known 2. Rese. 3. QuickStn 4. Z Coord 5. BS Check
④After the program record the station, Input level point, and press [ENT]. ※1)	Enter point name + [ENT]	Input PT
⑤Enter height of target prism, and press [ENT].	Enter height of target prism + [ENT]	Input PT

® Sight the center of prism, press [MSR1] or [MSR2] to start survey. If the horizontal circle is on Face-2, screen would display "Turn to F1". Rotate the telescope and alidade, and sight the BS point in Face-1.	Sight the target + [MSR 1]/ [MSR 2]	level point
The system finishes the measurement and displays the result.		level point
® Press [F2] and Rotate the telescope and alidade, and sight the center of target prism. Press [MSR1] or [MSR2]. If not measure on F2, press [ENT] and proceed to ①.	Rotate the telescope + [MSR 1]/ [MSR 2]	level point
	[ENT]	Ievel point
The result dialog box is displayed, press [OK] to confirm. To remeasure, press [Abrt].	[OK] or [Abrt]	Stn Setup dHA: 0°00′00″ dVA: -0°00′02″ dSD: 0.001 m * Press [ENT] Rec Labrat CP OK
(II)The updated station coordinates are displayed, the height Z is updated. You can change the HI in this screen.		N: 10.000 m E: 10.000 m Z: 6.180 m ST: 1 HI: 1.600 m
(12) Press [ENT] to record the updated STN. Screen returns to Stn Setup menu. **1) About method to input PtID, plear	[ENT]	1. Known 2. Rese. 3. QuickStn 4. Z Coord 5. BS Check




- When the HI is changed, the Z coordinate is updated before the station is recorded.
- You must complete a station setup before you use the Height Transfer function.

4.5 CHECKING AND RESETTING THE BACKSIGHT DIRECTION

STEP	OPERATION	DISPLAY
①In [Stn Setup] press [5] to enter into Backsight Check function.	[5]	
②Sight the BS point, and press	Sight the BS	BS Check
[Redo] or [ENT] to reset the	point	HA# 0°00′00″
horizontal angle to the HA set in last	+	BS: 7°21′28″
station setup. ※1). Press [Abrt] or	[Redo]/[ENT]	* BS Check
[ESC] to cancel the process and		Abrt Redo
return to the basic measurement		
TELUITI LO LITE DASIC ITTEASUTETTIETIL		
screen.		
		Display 1/5 HA# 7°21'28" VA# 87°04'21" SD# m PT: RUIDE HT: 1.000 m
Screen returns to the basic measurement screen, and HA is		HA# 7°21′28″ VA# 87°04′21″ SD# m PT: RUIDE

•You must complete a station setup before you use the BS check function.






5.1 STAKE OUT ANGLE AND DISTANCE


Specifying the stakeout point by angle and distance


STEP	OPERATION	DISPLAY
①Press numeric key [8] to enter into stake-out function. You should setup station and backsight azimuth before stake-out. Otherwise the screen displays as the right graph.	[8]	! Station not set 1.Continue 2.Stn Setup * Press [ESC]Abrt
②Press [Continue] to display ST, HI, and BS set in last operation. Shown as the right graph A. Press [OK] to confirm. Press [STN] to enter "Stn Setup" menu. Select one method to set station. Press [Abrt] to quit the program.		STN Check 1 1 1

	I	
③After the program record STN data, screen returns to SO main menu.		1. HA-HD 2. XYZ 3. PartLine 4. Ref. Line
④ Press [1] to display the input screen for the distance and angle to the target. Enter the values and press [ENT]. HD: Horizontal distance from station point to stakeout point dVD: Vertical distance from station point to stakeout point HA: Horizontal angle to stakeout point ※1)	[1]	HA-HD HD:1 dVD: HA:
⑤Start staking out. First Rotate the instrument until the dHA displays as 0°00′00″.		SO
©Sight the target and press [MSR1] or [MSR2] to start measuring.	[MSR 1]/ [MSR 2]	SO
Twhen the measurement is completed, the differences between the target position and the stakeout point are displayed. %2), %3) dHA: Difference in horizontal angle to the target point R/L: Right/Left (Lateral error) IN/OUT: In/Out (Longitudinal error) CUT/FIL: Cut/Fill		SO 1/8



	DISPLAY	DESCRIPTION
SO dHA ↔ L ↔ IN ↓ FIL ↑ * Pres	0°00′00″ 0.000 m 0.971 m 0.743 m	This page displays stake-out.








5.2 COORDINATES STAKEOUT

Input the XYZ of stakeout point, and carry on stake-out.

STEP	OPERATION	DISPLAY
①In SO menu, press [2] to enter into coordinate stakeout function.	[2]	SO
A: Enter the point name that you want to stake and press [ENT]. After finding the input point name, program proceeds to procedure 4. To display the coordinates, press [ENT] to confirm. B: Specify the point by code or radius from the instrument. (As shown in graph B). C: Specify a stakeout list by range input. To input points by range, press the Fr/To softkey in the PT field., as shown in right graph C. Enter the start point (Fr) and the end point (To). The last digit of point name must be a number. If existing points are found between Fr and To, a point list is displayed, see ③.		A: Input PT
③If several points are found, they are displayed in a list. Then use [▶]/[◀] and [▲]/[▼] to select needed point, and press[ENT]. ※2)		MP, 1, MP, 4 MP, 6 MP, 8

Screen displays coordinates of the selected point name., press [ENT] to confirm.	[ENT]	N: 10.020 m E: 10.004 m Z: 6.189 m PT: 1 CD: List Stac
⑤The delta angle and the distance to the target (HD) are shown. Rotate the instrument until the dAZ is close to 0°00'00", press [MSR1]/ [MSR2]. dHA: Difference in horizontal angle to the target point HD: Distance to the target point	[MSR 1]/ [MSR 2]	PT: 1 dAZ← 123°41′23″ HD# 7.071 m * Sight Press [MSR] OK
⑥After measuring, the deviation value between measure point and stakeout point is shown. ※1) dHA: Difference in horizontal angle to the target point R/L Right/Left (Lateral error) IN/OUT In/Out (Longitudinal error) CUT/FIL Cut/Fill		PT 1/8 dHA ♦ 0°00′00″ STP ♦ 0.000 m IN ■ 3.971 m FIL ↑ 0.743 m * Press [ENT] Rec
 ⑦Ask the rodman to adjust the target position. When the target is on the intended position, the displayed errors become 0 m. ♣: moving towards to station ♠: moving away from station 		SO 1/8
®When both R/L and IN/OUT display 0m, it indicates the prism is on the stakeout point. The fifth line shows the data of fill or dig.		SO
	[ENT]	N: 10.000 m E: 10.000 m Z: 6.180 m PT: 221 CD: List Stac



- $\,$ %1) Once a measurement is taken, the Cut/Fill value and Z coordinate are updated as the VA is changed.
- ※2) If you have assigned a control job, and additional points are found in the control job, the Ctrl softkey is displayed under the list.
- %3)Use the Add Constant field in [MENU]→[3.Set]→[6.SO] to specify an integer that is added to the point number being staked to generate a new number for recording the staked point.

For example, when you stake out PT3 with an Add Constant of 1000, the default number for SO record is 1003. When there are letters in the point name, put the Add Constant after the letter.


For example: When you stake out AD12 with an Add Constant of 1000, the default number for SO record is AD1012.

All observation results display in 8 pages: press [▼] or [DSP] to switch between display screens. Detailed introduction please refer to "HA-HD SO".

5.3 PARTLINE SO

This function divides the line between the instrument and the target by an input span number. It then guides you to stake out the points, one by one.

For example, if you measure to the end point at 100 m from the instrument and set the span total to 2, the following four points are calculated and can be staked.



STEP	OPERATION	DISPLAY
①In SO menu press [3] to enter into PartLine SO function.	[3]	SO ————————————————————————————————————
②Set up the baseline. Sight the target, and press [MSR1]/ [MSR2] to start survey. System set up a base line between the instrument and the measured point.	[MSR 1]/ [MSR 2]	PartLine HA# 123°41′23″ HD# * Sight Press [MSR]
③Enter the total stake number in Partition field, and press [ENT]. ※1)	Enter the total stake number + [ENT]	PartLine HA# 123 41'23" HD# 2.030 m Partition:
④The observation screen for the first stake (from the instrument) appears. Sight the prism and press [MSR1]/ [MSR 2].	Sight the first stake out point + [ENT]	PartLine <1/3> HD: 0.667 m L → OUT ↓ Prev Next
©When the measurement is completed, the differences between the target position and the stakeout point are displayed. ※2), ※3) HA: Difference in horizontal angle to the target point R/L: Right/Left (Lateral error) IN/OUT: In/Out (Longitudinal error)		PartLine <1/3> HD: 0.667 m STP
⑥ Ask the rodman to adjust the target position. When the target is on the intended position, the displayed errors become 0 m. ♣: moving towards to station ↑: moving away from station		PartLine <1/3> HD: 0.667 m STP ♦ 0.000 m STP ♦ 0.000 m *Press [ENT] Rec Prev Next



⑦If the third line "L/R" does not		PartLine <1/3>
display 0 m, ask the rodman to		HD: 0.667 m
adjust the target position.		STP • 0.000
→: Rodman moves to his left side.		m STP ♦ 0.000
←: Rodman moves to his right side.		m
		* Press [ENT] Rec
		Prev Next
®When both R/L and IN/OUT display 0m, it indicates the prism is on the stakeout point.		PartLine <1/3> HD: 0.667 m STP ♦ 0.000 m STP ♦ 0.000 m * Press [ENT] Rec. III Prev Next
 After staking out, your can press [ENT] to record the stakeout point. PT defaults to the last recorded PT+1, you can input code if necessary. Press [ENT] to record the point. 	[ENT]	N: 10.000 m E: 10.000 m Z: 6.180 m PT: 221 CD: List Stac
		PartLine <2/3> HD: 1.353 m L → OUT ↑ * Press [ENT] Rec Prev Next
 ※1) Use up or down arrowhead to change the guide point. ※2) Prev/[▼]: to the last stakeout point Next/[▲]: to the next stakeout point ※3) You can calculate and guide up to double the number of the stakes. 		

5.4 REFLINE STAKEOUT

This function allows you to stake out a point based on the Sta, O/S, and dZ to a specified line.

STEP	OPERATION	DISPLAY
①In [SO] menu press [4] to enter into Ref.Line stakeout function.	[4]	SO ————————————————————————————————————



	Enter the 1st	Input P1
②Enter the first point (P1) of the	point of the	P1:1
line. ※1)	line.	P2:
	+	ı ı
	[ENT]	Meas List Stac
	Enter the	Input P2
③Enter the second point (P2) of the	second point	P1:1 1
line.	of the line.	P2:
	+	
	[ENT]	Meas List Stac
4)Enter offsets to the line. Press		Input O/S
[ENT] in a blank field to enter the		STA:
value 0.0000.		O/S:
Sta: Distance from P1 along the	Enter offsets	dZ:
line.		* Dist to P1
O/S: Offset to beeline		
(+):Right side of the P1-P2 line		
(-): Left side of the P1-P2 line		
Dz: dVD to line		
⑤Start stakeout. Rotate the		Ref.Line <1/8>
instrument until the dAZ is close to		dAZ ← 23°41′23″
0°00'00" Sight the target and press	[MSR 1]/	
[MSR1]/[MSR2]	[MSR 2]	* Sight Press [MSR]
dAZ: Azimuth error to target point		OK
HD: Distance to target point		-
⑥After measuring, the deviation		PT 1/8
value between measure point and		dHA ♦ 0°00′00″
stakeout point is shown. ※1)		IN
dHA: Difference in horizontal angle		FIL 1 0.743 m
to the target point		* Press [ENT] Rec
R/L Right/Left (Lateral error)		TIESS [EXVI] Rec
IN/OUT In/Out (Longitudinal error)		
CUT/FIL Cut/Fill		
7Ask the rodman to adjust the		SO 1/8
target position. When the target is on		dHA ♦ 0°00′00″
the intended position, the displayed		STP 0.000 m STP \$ 0.000 m
errors become 0 m		FIL † 0.201 m
■: moving towards to station		* Press [ENT] Rec
1: moving away from station		




dig.	
After staking out, your can press [ENT] to record the stakeout point. PT defaults to the last recorded PT+1, you can input code if necessary. Press [ENT] to record the point. [ENT]	* Press [ENT] Rec N:
®After recording the point, the display returns to the SO screen. Press [ESC] to reinput the offsets. Repeat steps 4~9 to carry on Ref.Line stakeout. ×1) About method to input PtID, please refer to "	Input O/S

All observation results display in 8 pages: press [▼] or [DSP] to switch between display screens. Detailed introduction please refer to "HA-HD SO".



6. OS GHI KEY 6.1 DISTANCE OFFSETS



STEP	OPERATION	DISPLAY
①Press numeric key [9] to enter Offset function. You should setup station and backsight azimuth before offset measurement. Otherwise the screen displays as the right graph.	[9]	! Station not set 1.Continue 2. Stn Setup *Press [ESC] Abrt
②Press [Continue] to display ST, HI, and BS set in last operation. Shown as the right graph A. Press [OK] to confirm. Press [STN] to enter "Stn Setup" menu. Select one method to set station. Press [Abrt] to quit the program.		STN Check
③After the program record STN data, screen returns to Offset menu. Select O/S Dist.	[1]	Offset ————————————————————————————————————



④If you have not taken a distance measurement before entering this function, a temporary measurement screen appears. Sight the target and press [MSR 1]/[MSR 2].	[MSR 1]/ [MSR 2]	HA# 15°42′13″ VA# 264°01′13″ SD# HT: 1.000 m * Sight Press [MSR]
⑤Enter combination of distance offset to specify the point. After entering one item, press [ENT] moving to the next.	Enter combination of distance offset to specify the point.	O/S Dist R/L:1 O/I:
®The calculated coordinates are shown. Enter a PT and CD value, press [ENT] to record. The display returns to BMS. 1	[ENT]	N: 10.000 m E: 10.000 m Z: 6.180 m PT: 221 CD: 1
※1) Raw data is also recalculated, based on the distance offset value.		

6.2 MEASURING ANGLE OFFSETS

STEP	OPERATION	DISPLAY
①In [Offset] menu, press[2] to enter angle offset function	[2]	Offset ————————————————————————————————————
②If you have not taken a distance measurement before entering this function, a temporary measurement screen appears. Sight the target and press [MSR 1]/[MSR 2].	[MSR 1]/ [MSR 2]	HA# 15°42′13" VA# 77 '52′27" SD# HT: 1.000 m * Sight Press [MSR]
③The measuring results are shown. Press [DSP] or [▼] to view each dialog box of the results.	[DSP] or [▼]	O/S Ang. 1/5 HA# 15 '42'13" VA# 77°52'27" SD# 3.971 m Abrt OK



④To take the angle offset, rotate the alidade and telescope. The measured distance (HD) remains unchanged.		O/S Ang. 1/5 HA# 25°09'01" VA# 90°06'01" SD# 3.971 m Abrt OK
⑤To record the offset point, press [OK], and otherwise press [Abrt]. The XYZ data is also recalculated based on the new angle. In the dialogue box of results calculated by the program, press [ENT] Rec.	[OK]	HA: 25°09'01" VA: 90°06'01" SD: 2.228 m PT: 221 CD:
©The display returns to basic measurement screen.		Display 1/5 HA# 107°00′00″ VA# 75°52′27″ SD# PT: 222 HT: 1.600 m

You can record an angle offset in the basic measurement screen.

STEP	OPERATION	DISPLAY
①In basic measurement screen, press [MSR 1] or [MSR 2].	[MSR1]/ [MSR2]	Display 1/5 HA# 1°00′56″ VA# 94°26′10″ SD# 2.309 m PT: 222 HT: 1.600 m
② After taking a distance measurement, rotate the alidade and/or telescope. Press [DSP] or [▼] to view other pages of the result. You can see that the coordinates are changed with the change of angle.		Display 1/5 HA# 35°55'36" VA# 78°26'10" SD# 2.309 m PT: 222 HT: 1.600 m
③Then press [ENT] to record the measured distance with the updated angle value.	[ENT]	Rec Pt 26 A HT:



6.3 TWO-PRISM POLE

STEP	OPERATION	DISPLAY
①In [Offset] menu, press [3] to enter the 2Prism Pole function.	[3]	1. O/S Dist 2. O/S Ang. 3. O/S 2D 4. +HA Line □ 5. Input HD ↓
②Sight the first prism and press [MSR1]/[MSR2].	Sight the first prism + [MSR1]/ [MSR2]	O/S 2D <no. 1=""> 1/5 E HA# 15°42′13″ VA# 94°01′13″ SD# * Sight Press [MSR] OK</no.>
③Program enter measuring the second point automatically. Sight the second prism and press [MSR1]/[MSR2].	Sight the second prism + [MSR1]/	O/S 2D <no. 2=""> 1/5 HA# 43°19'14" VA# 91°11'47" SD# * Sight Press [MSR] OK</no.>
4 Enter the distance between the second prism and the target point. Alternatively, if you don't need QA information, you can leave the distance between the first and the second prism blank.	Input distances	InputDist
⑤If you entered a P1-P2 distance, the QA screen appears. Compare the entered value and the measured distance to check the accuracy of the observation. To reinput the distances, press [Redo] to return to step ④. To confirm, please press [OK] or [ENT] to step ⑥.		P1-P2 Dist InputDis 5.000 m Meas Dis 5.005 m Redo OK
©Press [ENT] to record the point.	[ENT]	Rec Pt 26 A HT:

Sample records CO,2Prism O/S:

66



P1-P2=5.000 (5.005), P2-Tgt=2.000

6.4 +HA LINE

This function is to extend a line by horizontal angle offset.

STEP	OPERATION	DISPLAY
①In [Offset] menu, press [4] to enter the line extension (+HA) function.	[4]	Offset 1. O/S Dist 2. O/S Ang. 3. O/S 2D 4. +HA Line 5. Input HD
②Sight the first prism (or target), press [MSR1]/[MSR2].	Sight the first prism + [MSR1]/ [MSR2]	+HA Line <no. 1=""> 1/5 HA# 15°42′13″ VA# 94°01′13″ SD# * Sight Press [MSR] OK</no.>
③Program enter measuring the second point automatically. Sight the second prism and press [MSR1]/[MSR2].	Sight the second prism + [MSR1]/ [MSR2]	+HA Line
4) Sight the alternative place on the same vertical line as the desired target point.		+HA Line < No. 2> 1/5 HA# 83°19'14" VA# 91°11'47" SD# 1.847 m * Sight < ALT> PT OK
⑤Press [OK] or [ENT] to calculate the coordinates and the raw data of the target point	[OK] or [ENT]	+HA Line < No. 2> 1/5 HA# 16°22′59″ VA# 36°11′39″ SD# 1.847 m * Sight <alt> PT</alt>



⑥Enter a PT (and CD) value, and	Enter a PT and	I	IA:	16°22′59″	
press [ENT] to Record the point.	CD value		/A:	36°11′39″	
The height of target is fixed to	+		SD:	5,228 m	
0.0000 for the offset point.	[ENT]	PI CI	C: 29 D:	â	
				List Stac	

The calculated point (TGT) is stored as a SS record.

Measurements to the first and second target (P1 and P2) are stored as comment records (PT1 and PT2). The last record records the angle measurement to the ALT (vertically offset point from the actual target point).

6.5 INPUT HD

This function is useful when the instrument is very close to the point and it is difficult to take a measurement using the EDM.

STEP	OPERATION	DISPLAY
①In [Offset] menu press [5] to enter into Input HD function.	[5]	1. O/S Dist 2. O/S Ang. 3. O/S 2D 4. +HA Line 5. Input HD
②Turn the telescope in the direction of the point that you want to store.		Input HD
③Enter the HD and press [ENT].	Enter the HD	Input HD 1/5 HA# 30°21′50″ VA# 115°52′45″ HD: 12,000 m * Sight press [ENT]
©Enter a PT (and CD) value and press [ENT], The target point is calculated and recorded as an SS record.	Enter a PT and CD + [ENT]	Rec Pt




6.6 CALCULATE A CORNER POINT

STEP	OPERATION	DISPLAY
①In [Offset] menu, press [▼] to display the second page of Offset. Press [6] to enter the corner point function.	[6]	
②Take a distance measurement to the first prism on the wall. Press [MSR1]/[MSR 2].	Sight the first point + [MSR1]/ [MSR2]	CornerPt <no. 1=""> 1/5 HA# 86°20'55" VA# 68°39'41" SD# * Sight Press [MSR]</no.>
③Sight a second point on the same wall and press [MSR1]/[MSR2]. ④Sight the third point on the second wall and press [MSR 1]/[MSR 2].	Sight a second point +[MSR1]/ [MSR2] Sight the third point + [MSR 1]/ [MSR 2]	CornerPt < No. 2> 1/5 HA# 96°06′38″ VA# 56°36′52″ * Sight Press [MSR] CornerPt < No. 3> 1/5 HA# 110°10′05″ VA# 52°00′41″ SD# * Sight Press [MSR]
⑤If the two walls are at right angles, press the Calc softkey to calculate the corner point by three points. If you take a measurement to a fourth point, the corner point can be calculated as the intersection of two walls (P1-P2 and P3-P4).	[Calc]	CornerPt < No. 4> 1/5 HA# 110°10'05" VA# 52°00'41" SD# 6.526 m * Press[MSR] or [Calc]




Enter PT and	Rec Pt
CD	PT:26 A
+	HT:1.000 m
[ENT]	<u> </u>
	List Stac
	CD +

6.7 COLUMN







- The calculated point (center of the circle) is stored as an SS record.
- If you press the +SD softkey before you sight Edge1, the input value is recorded at the end.

6.8 EXTEND THE SLOPE DISTANCE


0.0 = 0.7 = 0.0 = 0				
STEP	OPERATION	DISPLAY		
①In page 2 of [Offset] menu, press [8] enter the function for extending the slope distance	[8]	Offset		



②If you have not taken a distance measurement before entering this function, a temporary measurement screen appears. Sight the target and press [MSR1]/ [MSR2]. ③Enter the slope distance You can enter any value from -99.99 through +99.99m.Press [ENT] to record the point.	Enter the slope distance	HA#
④Enter a PT (and CD) value and press [ENT], The target point is calculated and recorded as an SS record.	Enter PT and CD + [ENT]	Rec Pt



7. PRGJIKL KEY 7.1 2 POINT REFLINE




STEP	OPERATION	DISPLAY
①In [Program] menu, press [1] to enter 2Pt.Ref.Line function.	[1]	Program
②Enter the first point for the reference line P1. ※1)	Input P1	InputP1
③Enter the second point for the reference line.	InputP2	InputP2
Sight the target and press [MSR1] or [MSR2] to start measurement.	[MSR1]/ [MSR2]	2Pt. Ref. L 1/5 STA# O/S# dZ# * Sight Press [MSR]
⑤After measuring, the results display. ※2) Sta: Horizontal distance from P1 to the measure point along the P1-P2 line O/S: Horizontal offset from the P1-P2 line to the measured point dZ: Vertical offset from the P1-P2 line to the measured point		2Pt. Ref. L 1/5 STA# 1.247 m O/S# -1.983 m dZ# -0.414 m * Sight Press [MSR] * Press [ENT] Rec.



⑥press [ENT] to record.	[ENT]	Rec Pt P1: HT: CD: Meas	1.0 List	11 1 00 m	
※1) About method to input PtID, please refer to "2.8 METHOD TO INPUT PTID".					
※2) Press [▲]/[▼] or [DSP] to view other pages.					

7.2 REFERENCE ARC

Measuring distance and offset values on the arc-curve.




STEP	OPERATION	DISPLAY
①In [Program] menu, press [2] to enter Ref. Arc function.	[2]	Program 1. 2Pt.Ref.L 2. Ref.Arc 3. MlmRadial Sta 4. Mlm Cont. 5. Rem 5. Rem
②Enter the start of the curve point P1. ※1)	Input P1	Arc Start P1: 1 AZ1:
		Meas List Stac
③Enter the azimuth of its tangent line (AZ1).	Input AZ1	Arc Start P1:1 1 AZ1:
		*Tangent A2 of P1



①Choose a method to define the arc, as shown in the graph.		1. P2-AZ2 2. Rad-AZ2 3. Rad-Len
A: Use P2-AZ2 to define arc. Input point name of P2 and azimuth of its tangent line (AZ2). ※2) B: Use Rad-AZ2 to define arc. Input the radial and azimuth of its tangent line (AZ2). In the radius (Rad) field, enter a positive value for a clockwise curve. Enter a negative value for a counterclockwise curve. As shown in graph B. C: Use Rad-Len to define arc. Input radial and arc length. Similarly, in the radius (Rad) field, enter a positive value for a clockwise curve. Enter a negative value for a counterclockwise curve. Enter a negative value for a counterclockwise curve. As shown in graph C.		A: Define Arc
©When all factors have been entered, the instrument calculates the curve. If the curve length (Len) is too large for a circle of the given radius, it is shortened. If the curve is reasonable, press [OK] to confirm. Otherwise press [Abrt] to redefine. ©Sight the center of prism, and press [MSR1] or [MSR2].	[OK] or [Abrt] [MSR 1]/ [MSR 2]	Ref.Arc Rad: 8.000 m Len: 8.378 m AZ2: 62°00′00″





7.3 REMOTE DISTANCE MEASUREMENT

This function measures the horizontal distance, vertical distance, and slope distance between two points.

User can select between two different methods:

MimRadial(A-B, A-C)

Mim Cont. (A-B, B-C)

rSD: Slope distance between two points

rHD: Horizontal distance between two points

rVD: Vertical distance between two points

RV%: rV% Percentage of grade (rVD/rHD) x 100%


rGD: Vertical grade (rHD/rVD)

rAZ: Azimuth from first point to second point



7.3.1 MimRadial

Measuring between the current and the first point measured



STEP	OPERATION	DISPLAY
①In [Program] menu, press [3] to enter MimRadial function.	[3]	Program 1. 2Pt.Ref.L 2. Ref.Arc P3 3. MlmRadial P4 4. Mlm Cont. 5. REM
②Sight the first point and press [MSR1]/[MSR2].	Sight the first point + [MSR1]/ [MSR2]	MimRadial 1/2 rSD# rVD# rHD# * Sight Press [MSR]
③The distance from the station point to the first point is displayed.		MimRadial 1/2 rSD# 2.287 m -0.174 m rHD# 2.280 m * Sight Press [MSR] * Press [ENT] Rec.


RUIDE

	Sight the second point + [MSR1]/ [MSR2]	MimRadia 1/2 rSD# 2.593 m rVD# 0.016 m rHD# 2.593 m * Sight Press [MSR] * Press [ENT] Rec. The result in second page: MimRadia 1/2 rAZ# 41 37'02'' rV%# 0.63% rGD# 158.114:1 * Sight Press [MSR] * Press [ENT] Rec.
©After recording, the display returns to MimRadial screen, sight the third point and press [MSR 1]/[MSR 2], the distances between the first and second point are displayed.	Sight the third point + [MSR1]/ [MSR2]	MimRadial 1/2 rSD# 7.782 m rVD# -1.073 m rHD# 7.700 m * Sight Press [MSR] * Press [ENT] Rec.
⑦Press [ENT] to record the distances between the first and second point. Repeat steps ④~⑤ to calculate and record the distance between the first point and other points.	[ENT]	Rec CO Data



7.3.2 Mim Cont.

Measuring between the current point and the immediately preceding point. Other operations are same as MimRadial.




STEP	OPERATION	DISPLAY
① In [Program] press [4] to enter Mim Cont. function.	[4]	Program 1. 2Pt.Ref.L 2. Ref.Arc 2. Ref.Arc 3. MlmRadial 4. Mlm Cont. 5. REM
②Sight the first point and press [MSR1]/[MSR2].	Sight 1st point + [MSR1]/ [MSR2]	Mim Cont. 1/2 rSD# rVD# rHD# * Sight Press [MSR] 1
③The distance from the station point to the first point is displayed.		Mim Cont. 1/2 rSD# 7.782 m rVD# -1.073 m rHD# 7.700 m
④ Sight the second point and press [MSR1]/[MSR2], the distances between the first and second point are displayed. rSD: Slope distance between two points rVD: Vertical distance between two points rHD: Horizontal distance between two points.	Sight the second point + [MSR1]/ [MSR2]	MimRadial 1/2 rSD# 8.402 m rVD# -0.133 m rHD# 8.401 m * Sight Press [MSR] * Press [ENT] Rec.



Press [▲] or [▼] to display next		The second page:
page.		MimRadial 1/2
rAZ: Azimuth from first point to		rAZ# 77°51′00″
second point		rV%# -1.58% rGD# -63.372:1
rV%: Percentage of grade		* Sight Press [MSR]
rGD: Vertical grade (rHD/rVD)		* Press [ENT] Rec.
⑤To record the distance and angle		Rec CO Data
information as a comment record,		Fr:1 1
press [ENT] in the 1/2 or 2/2		То:2
observation screen.		ñ
Default point numbers are		List Stac
displayed. (STN=0, PT=1, PT=2,		
PT=3), it can be changed.		
⑥After recording, the display	Sight the third	MimRadial 1/2
returns to MimRadial screen, sight	point	rSD# 2.593 m
the third point and press [MSR	+	rVD# 0.016 m
1]/[MSR 2], the distances between	[MSR1]/	* Sight Press [MSR]
the second and third point are	[MSR2]	* Press [ENT] Rec.
displayed.		
⑦Press [ENT] to record the		Rec CO Data
distances between the first and third		Fr:2 1
point. Repeat steps $\textcircled{4}\sim \textcircled{5}$ to	[ENT]	То:3
calculate and record the distances		ñ
between the third point and the		List Stac

7.4 REMOTE ELEVATION MEASUREMENT (REM)






- 1: Target point 2: Vh
- 3: Slope Distance 4: Base point

3: Slope Distance 4:	OPERATION	DISPLAY
SIEP	OPERATION	
①In [Program] press [5] to enter REM function.	[5]	1. 2Pt.Ref.L 2. Ref.Arc 3. MlmRadial 4. Mlm Cont. 1 5. REM
②Enter the height of target HT.	Enter the height of target	REM HT: 0.000 m Vh: * Input HT first Stac
③Sight the target point and press [MSR1]/[MSR2].	Sight the target point + [MSR1]/ [MSR2]	REM HT: 1.620 m Vh: * Sight Press [MSR]
4The measuring results are displayed.		REM HT: 1.620 m Vh: 1.620 m * Press [ENT] update HT □
⑤Loosen the vertical clamp, and turn the telescope to aim at the target point. The difference in elevation (Vh) is displayed.	Sight the target point	REM HT:
⑥You can press [ENT] to update the height of target.	[ENT]	REM HT: -1.977 m Vh: 0.000 m * Press [ENT] update HT



7.5 2-PT REFERENCE PLANE (V-PLANE)

Measuring distance and offset values on the vertical plane.




STEP	OPERATION	DISPLAY
①In the second page of [Program] press[6] to enter 2-Pt Reference Plane (V-Plane) function.	[▼] [6]	Program 6. V-Plane 7. S-Plane 8. Roads
②Input the first point to define the plane. ※1)	InputP1	InputPl
③Input the second point on the vertical plane, and press [ENT].	InputP2	InputP2
①Once the plane is defined, the calculated Sta and dZ values are updated as you move the telescope. No distance measurement is required. Sta: Horizontal distance from P1 to the target point along the baseline		V-PLANE 1/3 STA: -3.815 m dZ: -0.153 m * STA: is P1-P2 line to P1 dist 2/3: V-PLANE 2/3
dZ: Vertical distance from P1 to the target point Press [▼] to display other pages. As shown in the right graph.		N: 0.711 m E: 3.860 m Z: -0.516 m * INT of collimator and plane is XYZ



		3/3: V-PLANE 1/3 HA# 78°45′19" VA# 162°30′26" * Press [ENT] Rec.	
⑤To record the point, press [ENT] on any screen. Input PT and CD and then press [ENT] in the dialog box shown as the right graph.	[ENT]	HA: 78°45′19″ VA: 162°30′26″ SD: 13.333 m PT: 221 CD:	
※1) About method to input PtID, please refer to "2.8 METHOD TO INPUT PTID".			

7.6 3-PT REFERENCE PLANE (S-PLANE)

Measuring distance and offset values on the slope.




STEP	OPERATION	DISPLAY
①In the second page of [Program] press [7] to enter 3-Pt Reference Plane (S-PLANE) function.	[▼] [7]	6. V-Plane 7. S-Plane 8. Roads



②Input the first point to define the slope plane.	Input P1	InputP1
③Input the second point.	Input P2	InputP1
④Input the third point on the plane. If press [2PT] here, the program will define the plane by P1 and P2. ※1)	Input P3	InputP1
⑤Once the plane is defined, the calculated a and b values are updated as you move the telescope. No distance measurement is required. a: Distance between P1 and the point that is perpendicular to the target point along the P1-P2 line b: Length of the perpendicular line from the target point to the P1-P2 line Press [▼] to display other pages. As shown in the right graph.		S-PLANE 1/3
©To record the point, press [ENT] on any screen. Input PT and CD and then press [ENT] in the dialog box shown as the right graph.	[ENT]	HA: 107°49′29″ VA: 262°16′00″ SD: 41.502 m PT: 221 CD: List Stac



%1) If the plane is defined by two points, the vertical plane is the same as the plane used in the V-Pln function, but the indicating factors are Sta and dZ, not a and b.



7.7 ROADS

This program enables you to easily define a line or curve or spiral as a reference for measurements and stake outs. It supports chainages, as well as incremental stake-outs and offsets.

Before starting road design and stake-out, user should set job, station, and orientation first.

Roads 1. HZ Alignment 2. VT Alignment 3. Stn Setup 4. Stake Out Roads

7.7.1 Define HZ Alignment

Horizontal alignment consists of the following elements: start point, line, curve and spiral.


To define a horizontal alignment, user should first input the detailed information (Chain, N, E coordinate) of start point.

Start Pt	01
CH: 0.000	
N : 0.000 m	
Е:	
	Ô

Serial number and the amount of present horizontal alignment are displayed on the upper right corner of the screen.

The element of start point consists of the start chainage and E, N coordinate of start point. Enter these details, and press [ENT] to display the main line inputting screen.





The screen displays: current chainage, the azimuth angle of the tangent on the chainage, and the function key of the establishing new line. The system provides four functions: defining line, curve, spiral, and point.

Select a function key, enter the detailed information of the chainage, the alignment elements will be created. Press [ENT] to calculate the new chainage and azimuth angle automatically and return to the alignment defining main menu. Now other line type can be defined.

OPERATION	DISPLAY
[▼] [8]	6. V-Plane 7. S-Plane 8. Roads
[1] + [ENT]	Roads 1. HZ Alignment 2. VT Alignment 3. Stn Setup 4. Stake Out Roads
[1]	HZ Alignment 1. Define HZ AL 2. Edit HZ AL 3. Receive HZ AL 4. Delete HZ AL
Input chainage of start point, N, E coordinates	Start Pt 01 CH: 0.000 N: 0.000 m E: 0.000 m
	[V] [8] [1] + [ENT] [1] Input chainage of start point, N, E coordinates




⑤The display enters into the Define HZ alignment main menu.	Define CH: AZ:	HZAL		01 1.000 00'00''
	Str	Arc	Trns	Pt

Straight Line

When the start point or other line type is defined, user can define line. A line consists of azimuth angle and distance. The distance value can not be negative.

STEP	OPERATION	DISPLAY
①In Define HZ AL screen press [Str] to enter into the straight line defining menu.	[Str]	Define HZ AL 01 CH : 1.000 AZ : 0°00'00" Str Arc Trns Pt
②After inputting AZ angle, press	Input AZ angle	Straight 02
[ENT] to go to next input item. After	[ENT]	AZ : 0°00′00″ Len :
inputting the length of the line, press	Input Length	
[ENT].	[ENT]	
③The display returns to alignment		Define HZAL 02
defining main menu, and displays		CH: 11.000 AZ: 25°00′00″
chainage of the line, end point and		25 00 00
azimuth of this point.		
Now, user can define other curves.		Str Arc Trns Pt
When the line is in the middle of		
road, the azimuth angle of the line is		
calculated according to the previous		
elements. If user is to change this		
azimuth angle, the new azimuth		
angle can be input manually.		

<u>Arc</u>






Press [ARC] in "Define HZ AL" menu to define the arc. A curve consists of arc length and radius. The rule of radius value: along the forward direction of the curve. When the arc turns right, the radius value is positive; while the arc turns to left, the radius value is minus. The arc length can neither be negative nor longer than the circumference.

STEP	OPERATION	DISPLAY
①In Define HZ AL screen press [Arc] to enter into defining arc screen.	[Arc]	Define HZ AL 01 CH : 1.000 AZ : 0°00'00" Str Arc Trns Pt
②Input radius and arc length, and press [ENT] to record this data.	Input radius and arc length + [ENT]	Arc 02 Rad : Len :
③The display returns to alignment defining main menu, and displays chainage of end point of the arc and azimuth of this point.		Define HZAL 02 CH: 20.000 AZ: 85°22′30″ Str Arc Trns Pt

Transition




In Define HZ AL screen press [Trns] to define transition. A transition consists of the minimum radius and arc length. The rule of radius value is same as the rule of radius value. Similarly, the arc length can't be negative.

RUIDE

STEP	OPERATION	DISPLAY
①In Define HZ AL screen press [Trns] to enter into defining transition screen.	[Tms]	Define HZ AL 01 CH : 1.000 AZ : 0°00′00″ Str Arc Trns Pt
②Input radius and arc length, and press [ENT] to record this data.	Input radius and arc length [ENT]	Transition 02 Rad: Len:
③The display returns to alignment defining main menu, and displays chainage of end point of the transition and azimuth of this point.		Define HZ AL 01 CH: 15.000 AZ: 73°45′17" Str Arc Trns Pt

Point



In Define HZ AL screen press [Pt] to define point. A point element consists of coordinate, radius and spiral factors A1 and A2. Radius, A1 and A2 can not be negative. As radius is entered, an arc with specified radius inserted between current point and next point. As spiral factors A1 or A2 are entered, a curve with specified length is inserted between line and arc.

Note: If user input A1, A2 from according to the lengths L1, L2 of spiral, the following formulas are used to calculate A1 and A2.

$$A_i = \sqrt{\sum_i \text{Radiu}}$$

$$A_2 = \sqrt{L_2 \text{ Radiv}}$$



STEP	OPERATION	DISPLAY
①In Define HZ AL screen press [Pt] to enter into defining point function.	[Pt]	Define HZ AL 01 CH : 1.000 AZ : 0°00′00″ Str Arc Trns Pt
②Input N and E coordinates, radius and A1, A2, then press [ENT].	Input N, E coordinates, radius and A1, A2 [ENT]	Pt 02 N: 0.000 m E: 0.000 m Rad: 0.000 m A1: 0.000
③The display returns to the alignment defining main menu.		Define HZ AL 02 CH : 21.000 AZ : 100°00′51″ Str Arc Trns Pt

7.7.2 Edit Horizontal Alignment Data

In the process of defining horizontal alignment, editing is available.

Straigh	ht		
02/05			
AZ :		20°00′00″	
Len:		10.000 m	l <u>.</u>
			Î
Strt	End	Prev	Next

Soft keys:

[Strt]: Go to the beginning of the file, and displays the first alignment data.

[End]: Go to the end of the file, and displays the last alignment data.

[Prev]: Display the previous point data.

[Next]: Display the next point data.

It is possible to edit data by using the function keys above. After entering the data to be edited, press [ENT] to record the edited data and enter into the inputting screen of next point. To quit without saving data, press [ESC].

STEP	OPERATION	DISPLAY
① In HZ Alignment select "Edit HZ AL".	[2]	HZ Alignment 1. Define HZ AL 2. Edit HZ AL 3. Receive HZ AL 4. Delete HZ AL



②Screen displays the start point data. Press [Next] softkey to find the alignment data needed to edit.	[Next]	Start Pt 01/05 CH: 10.000 N: 10.000 m E: 10.000 m End Next
③Input the new data and press [ENT].	Input new data + [ENT]	Straight 02/05 AZ: 30°00′10″ Len: 10.000 m Strt End Prev Next
Screen displays the modified new data. Press [Prev] or [Next] to view and modify other data.		Straight 02/05 30°00′10″

7.7.3 Receive HZAL

STEP	OPERATION	DISPLAY
①In HZ Alignment select "Receive HZ AL"。	[3]	HZ Alignment 1. Define HZ AL 2. Edit HZ AL 3. Receive HZ AL 4. Delete HZ AL
②Press [Comm] to set communication parameter, making the parameter consistent with the setting in communication software. If not transmit, press [Abrt]. Press [▲]/[▼] to move cursor to each parameter, press [◀]/[▶] to select options of each item. After	[Comm]	Receive HZAL Abrt Comm Strt Press [Comm]: <comm> Baud: 1200 Data.L: 8 Parity: None</comm>
finishing setting, press [ENT].		Stop: 1 Receive HZAL
After setting, press [Strt] to receive.	[Strt]	Receive



⑤After receiving data, the program		
quit automatically, and returns to HZ		
Alignment menu.		

7.7.4 Delete Horizontal Alignment Data


The horizontal alignment data in internal memory can be deleted. Operation is shown below.

Shown delow.	OPERATION	DISPLAY	
3157	OPERATION	DISPLAT	
①In HZ Alignment select "Delete HZAL".	[4]	HZ Alignment 1. Define HZ AL 2. Edit HZ AL 3. Receive HZ AL 4. Delete HZ AL	
②The program displays as the graph:		Delete HZ AL *Sure? Abrt OK	C
③Press [OK] to delete horizontal alignment data, all the horizontal alignment data in internal memory will be deleted. The system returns to HZ Alignment screen. User may re-define horizontal alignment data. (Here, taking deleting horizontal alignment data for example) Press [Abrt] if it is not to be deleted.	[OK]	HZAlignment 1. Define HZAL 2. Edit HZAL 3. Receive HZAL 4. Delete HZAL	



7.7.5 Define Vertical Alignment

A vertical alignment consists of a series of intersections, including a chainage, height and curve length. The length of start point and end point must be zero.



Intersections can be entered in any order. After entering one point data, press [ENT] to save it and go to next inputting screen. Press [ESC] to quit without saving.

STEP	OPERATION	DISPLAY
①In Roads menu select "2.VT Alignment" to enter into define VT Alignment function.	[2]	Roads 1. HZ Alignment 2. VT Alignment 3. Stn Setup 4. Stake Out Roads
②Select "Define VT AL".	[1]	VT Alignment 1. Define VT AL 2. Edit VT AL 3. Receive VT AL 4. Delete VT AL
③Input chainage, elevation and length, then press [ENT]. The length of start point and end point must be 0.	Input chainage, elevation and length + [ENT]	Define VT AL 01 CH: 10.000 ELEV: 20.000 m Len: 0.000 m
④At the bottom of the screen "Complete" displays, saving this alignment data, the display returns to Define VT AL screen to continue inputting the next alignment.		Define VT AL 01 CH : 0.000 ELEV : 0.000 m Len : 0.000 m



7.7.6 Edit Vertical Alignment Data

It is able to be applied to edit vertical alignment data. The operation steps are similar to that of editing horizontal alignment.

STEP	OPERATION	DISPLAY
① In VT Alignment select "Edit VT AL".	[2]	VT Alignment 1. Define VT AL 2. Edit VT AL 3. Receive VT AL 4. Delete VT AL
②Screen displays the first Vertical alignment. Use softkey [Next] to find other alignment that needs to be edited.	[Next]	Edit VTAL 01/05 CH: 10.000 ELEV: 10.000 m Len: 0.000 m End Next
③Input new data and press [ENT].	Input new data + [ENT]	Edit VT AL 03/05 CH: 50.500 ELEV: 30.000 m Len: 60.000 m Strt End Prev Next
Screen displays the modified new data. Press [Prev] or [Next] to view and modify other data.		Edit VT AL 03/05 CH: 50.500 ELEV: 10.000 m Len: 20.000 m End Next

The method of Receiving VT AL data is same as Receiving HZ AL data. Please refer to "7.7.3 Receive HZ AL data".

7.7.7 Delete Vertical Alignment Data

The vertical alignment data in internal memory can be deleted. Operation is shown below.


STEP	OPERATION	DISPLAY
①In VT Alignment select "Delete VT AL".	[4]	VT Alignment 1. Define VT AL 2. Edit VT AL 3. Receive VT AL 4. Delete VT AL
②The program displays as the graph:		Delete VT AL *Sure? Abrt OK



③Press [OK] to delete VT AL, all the vertical alignment data in internal memory will be deleted. The system returns to VT Alignment screen. User may re-define vertical alignment data. (Here take deleting vertical alignment data for example) Press [Abrt] if it is not to be deleted.	[OK]	VT Alignment 1. Define VT AL 2. Edit VT AL 3. Receive VT AL 4. Delete VT AL	Û
---	------	---	---

7.7.8 Stn Setup

You can use chainage to setup station when there is horizontal alignment data in internal memory.



STEP	OPERATION	DISPLAY
①In Roads menu select"3.Stn Setup".	[3]	Roads 1. HZ Alignment 2. VT Alignment 3. Stn Setup 4. Stake Out Roads
②When there is horizontal alignment data in memory, you can use [CH] to setup station. Other method to setup station, please refer to "4. [TN ABC] Key". Press [CH] to start.	[CH]	Input STN
③Input the chainage and press [ENT]. Make sure the input chainage is on the designed horizontal alignment. Press [PT] to enter into setting up station by point function, refer to "4. The Key".	Input chainage + [ENT]	Input STN CH:



④In OF item input the offset of the chainage to center line. And press [ENT].	Input Offset + [ENT]	Input STN 100.000 OF: 0.000 m HI: 0.000 m
⑤The screen displays detailed data about the chainage. Input height of instrument and press [ENT].	Input height of instrument + [ENT]	Input STN CH: 100.000 OF: 1.000 m HI: 0.000 m
©Set backsight point. Backsight point can be also set by chainage. Same as "4. FIN ABC Key".		Backsight 1. XYZ 2. Angle

7.7.9 Stake out Roads


To stake out alignment, the alignment type should be defined first. 2 methods of defining horizontal alignment are available: installing in the computer via the data communication software provided by *Sanding Optic-Electric Equipment Co., Ltd*; or inputting manually in program "Road".

The vertical alignment data is unnecessarily to be defined, unless it is required to compute dig and fill. The method to define is similar to that of horizontal alignment. **Rules of alignment stake-out data:**

Offset left: Horizontal distance between the left chainage and central line.

right: Horizontal distance between the right chainage and central line.

Vertical Difference Left (right): vertical difference between left (right) chainage and the central line point.





In the process of stake-out, user should first stake out points on the central line, then the featured points on both sides.

The method to stake out alignment is similar to that of point stake-out, with 3 methods available:

Take points on the central line for example.

STEP	OPERATION	DISPLAY
①In Roads menu select "4. Stake Out Roads".	[4]	Roads 1. HZ Alignment 2. VT Alignment 3. Stn Setup 4. Stake Out Roads
②Displays the alignment stake-out data. Input start chainage, chainage increment, and the horizontal distance between side chainage point and central line. Height distance is required if fill/dig data is to be staked out. O/S L: Horizontal distance between the left chainage point and central line. O/S R: Horizontal distance between the right chainage point and central line. dVD L: Height difference between the left chainage point and central line dVD R: Height difference between the right chainage point and central line	Input data + [ENT]	StartC:
③After the data is input, press [ENT] to enter into the main screen of displaying stake-out point and offset. (See the introduction to Stake-Out Main Menu behind.) Here shows the stake-out data of central line of start chainage.		CH: 1.000 O/S: 0.000 m dVD: 0.000 m * Press [MENU] Slope SO LOFS ROFS +CHG -CHG



		
①Steps: Stake out points on the central line first, and then press [LOFS](or [ROFS]) to stake out (or right) chainage. Press [LOFS] (or [ROFS]), the relative chainage, offset, height difference will be displayed on the screen. Chainage and height difference can be input manually here. Offset is negative: Offset point is on the left of central line. Offset is positive: Offset point is on the right of central line.		CH: 1.000 O/S: 0.000 m dVD: 0.000 m * Press [MENU] Slope SO LOFS ROFS +CHG -CHG
©When the chainage and the offset to be staked out occurs, press [ENT] to enter into stake-out screen. Press [ENT] to save the coordinates of the stake-out point Program enters into road stake-out screen automatically. Not to save, press [SO].		N: 10.000 m E: 10.000 m Z: 6.180 m PT: 221 CD: SO List Stac
©Enter into the Stake Out Roads screen. The Operational steps are same as point stake-out. Rotate the instrument until the dAZ displays 0°00'00".		Stake Out Roads dAZ→ 48°56′52″ HD: 14.972 m * Sight Press [MSR] OK
⑦Sight the target and then press [MSR 1] or [MSR 2].	[MSR 1]/ [MSR 2]	Stake Out Roads



®After measuring, the deviation value between measure point and stakeout point is shown. %2), %3) dHA: Difference in horizontal angle to the target point R/L: Right/Left (Lateral error) IN/OUT: In/Out (Longitudinal error) CUT/FIL: Cut/Fill		Stake Out Roads 1/8
 ③Ask the rodman to adjust the target position, making R/L and IN/OUT to display 0 m. I moving towards to station moving away from station 		Stake Out Roads 1/8 dHA
		Stake Out Roads 1/8 dHA
(II)After staking out, your can press [ENT] to record the stakeout point. PT defaults to the last recorded PT+1, you can input code if necessary. Press [ENT] to record the point.	[ENT]	N: 10.000 m E: 10.000 m Z: 6.180 m PT: 221 CD: List Stac

Explanation for the Alignment Stake-Out screen:



LOFS: This key is used to stake out left chainage. Press it to display the offset and the height difference of the left chainage.

ROFS: This key is used to stake out right chainage. Press it to display the offset and the height difference of the right chainage.

+CHG: The key is used to increase the chainage.

-CHG: The key is used to increase the chainage.




7.7.10 Slope Stake-out

Slope Stake Out can be launched as part of the Alignment Stake-Out. It is a must to define horizontal and vertical alignments in Road menu previously. In stake-out main screen, press [menu] to enter into slope stake-out function.

Slope stake-out screen:


Slope SO	
(1: N))
Cut L:	0.000
Fill L:	0.000
Cut R:	0.000
Fill R:	0.000

The fill/ cut value that are input here is a ratio.



The fill/dig data can be entered through left and right slopes. In terms of fill/dig, use positive symbol to input the required slope, the software selects an appropriate slope in the list according to the actual position of the point.

Dig/fill is decided via the estimated height of hinge point. If the height is above the hinge point, the dig slope is used; otherwise the fill slope is used.





STEP	OPERATION	DISPLAY
①In the Stake-out main menu, input (or select) the side chainage to be slope staked out. Press [MENU] to start.	[MENU]	CH: 1.000 O/S: 0.000 m dVD: 0.000 m * Press [MENU] Slope SO LOFS ROFS +CHG -CHG
②Input the ratio of left and right slopes to be filled (or digged). After finishing inputting one item, press [ENT].	Input slope + [ENT]	Slope SO (1: N) Cut L: 0.000 Fill L: 0.000 Cut R: 0.000
③When all data are input, select the left (or right) slope to be staked out.		Select (Left) or (Right) Cut L: 1.000 Fill L: 2.000 Cut R: 2.000 Fill R: 3.000 Interpretation of the state
④Enter into the screen of Slope Stake Out function, input prism height, collimate the point that is to be intercepted near the slope, and press [MSR1] or [MSR2] to start slope stake-out. The system will select an appropriate slope from the data input in last Step. Suppose to set the height of measurement point as the horizontal datum plane, calculate the intercepted point. The list displays the offset between measurement point and calculated point.	[MSR1]/ [MSR2]	Slope SO HD: * Sight Press [MSR]
⑤The method to stake out slope is similar to that of point stake-out. When both second line and third line are zero, it indicates that the stake-out point is found.		Slope SO R



© After finishing staking out this point, press [ESC] to return to the main screen of Slope Stake Out, input other slope to be staked out to proceed the stake-out of next slope via the same approach.

Select (Left) or (Right)

Cut L: 1.000

Fill L: 2.000

Cut R: 3.000

Left Right

Note:

- 1) If the earth surface crosses the hinge point, the intersection cannot be calculated.
- 2) As the fill/dig value of calculated point is zero, therefore the fill/dig value is not displayed.





In basic measurement screen, press to change the default feature code that will appear in the CD item when you record a point.

Update the default code

STEP	OPERATION	DISPLAY
①In basic measurement screen, press [5] (Code) key.	[5]	Display 1/5 AZ# 280°56′10″ HD# 46°29′06″ SD# PT: 1 HT: 1.000 m
②A window for entering the feature code appears.		InputCod A CD:
③※1) A: Input the CD manually. The input code will be entered into Stac in chronological order.		A: InputCod A CD:RUIDE List Stac B:
B: Select code from [List] window to input. To add, delete or edit code in the List, please refer to "11.4.14 Point Name List and Code List" C: Select code from [Stac] to input.		AD 1 3 ER B D
Any place to input code manually can realize code Stac. The stack shows the last 20 point names used, in chronological order from last used to first used.		C: LIBA XIEPO LUDENG DUIDEYIQ LUBIAO FANGW



Rec Pt	①press [ENT] to return to BMS.	[ENT]	Display 1/5 AZ# 280°56′10″ HD# 46°29′06″ SD# PT: 1 HT: 1.000 m
© Press [Rec/Ent] to see if the default code is the setting you just do. PT:	default code is the setting you just		PT: 26 A HT: 1,000 m CD: RUIDE

RUIDE

9. DAT POR KEY

When you press [DAT] in the basic measurement screen or in observation screens in functions such as Stakeout, 2Pt RefLine, etc., the data in the current job is displayed.

Hold [DAT] for one second in the basic measurement screen or an observation screen to display the Data Type screen. Through this screen you can change the type of data that is assigned to [DAT].

- •To change the type of data that is assigned to [DAT], go to [MENU] \rightarrow [6.1 Sec.] \rightarrow [5.Data]
- •For more information, see "11.4 VIEW RECORDS".



10. USRI STU / USR²VWX KEY

If you use a certain function frequently in the field, you can assign it to the [USR1] or [USR2] key. Whenever you press a [USR] key, the function which is predefined is activated directly.

The following functions can be assigned to the [USR] keys:

Input HT

BS Check

TGT

Cogo→

Offset→

Program→

Temp&Press

Note

Point Laser

Direction Laser

(none)

STEP	OPERATION	DISPLAY
①In basic measurement screen,		Display 1/5
press [USR1]/ [USR2] for 1 sec,	Press [1] for 1	AZ# 280°56′10″
the function list of [USR] will	second	HD# 46°29′06" SD#
display. (Here take USR 1 as		PT:1
example.)		HT: 1.000 m
②Press [▲]/[▼] to highlight the		【User 1】
function and then press [ENT].		Input HT
※1), ※2)		BS Check TGT
If an item on the list has an arrow	[▲]/[▼]	Cogo→
"→" beside, and if you select this	+	* Offset→
item, the whole menu is assigned	[ENT]	<u> </u>
to the [USR] key. To assign a		Cogo (Menu)
specific function from the		Inverse→
sub-menu, press [▲]/[▼] to		AZ&Dist→ Area
highlight the function. Then press		LineOff.
[ENT].		Input XYZ
		Display 1/5
③The screen returns to basic		AZ# 280°56′10″
measurement.		HD# 46°29'06"
		PT:1
		HT: 1.000 m



- %1) The current predefined function is indicated by an asterisk (*) beside the function name.



11. MENU KEY

Press [MENU] to display the MENU screen.

11.1 JOB

11.1.1 Open a Job

STEP	OPERATION	DISPLAY
①Press [Menu] key, a screen shows as the right graph.	[Menu]	
②Press [1] to open the Job Manager. ※1)	[1]	JobMgr. * RUIDE 07-01-20 @ MQ 07-01-25 RTS800 07-01-25 SURVEY 07-01-25 New Del Ctrl Info
②Select the item by [▲]/[▼], and then press [Ent] to open the job. ※2)	[▲]/[▼]	JobMgr. * RUIDE 07-01-20 @ MQ 07-01-25 RTS800 07-01-25 SURVEY 07-01-25 New Del Ctrl Info
③Program sets the item as current item, and returns to basic measurement screen.		Display 1/5 HA# 20°00′00″ VA# 87°04′21″ SD# m PT: RUIDE HT: 1.000 m

^{※1)}If there are no job stored, the CreatJob screen appears.

The meaning of the symbol:

- * Current job
- @ Control job
- ! Some of the job settings are different from the current job.

^{*2)}When you open a job, all job settings are automatically changed to match those used in the opened job.



11.1.2 Create a New Job

STEP	OPERATION	DISPLAY
①Press [New] in the job list.	[New]	Job Mgr. * RUIDE
②Enter a job name (within eight characters), and press [Ent]. ※1)	Enter a job name + [Enter]	Create Job Job: *Max 8 char
③To confirm setting a new job, press [OK] or [Enter]; To input a name again, press [Abrt]; To check the settings of the job, press [Set]. ※2)	[OK] Or [Enter]	Create Job Job: RUIDE800 * Press [OK] creat

^{※1)} Within 8 characters.

Job Settings

The following 12 settings are set when a job is created, and they can't be changed. It is different from other temporary settings. It ensures that the data in a job is correctly stored in the database and that all necessary corrections are applied when you store each record.

Item	Option
Scale	0.99000~1.01000
T-Pcrn.	ON/OFF
SeaLevel	ON/OFF
C&R crn	OFF/0.14/0.200
Angle	DEG/GON/MIL
Dist	Meter/USA Feet/USA Inch/IntlFeet/IntlInch
Temp	°C/ °F
Press	hPa/mmHg/inHg
VA 0	Zenith/ Vertical/Vert±90
AZ 0	North/ South
Order	NEZ/ENZ
НА	Azimuth/0 to BS

^{%2})If it is not necessary to change last setting, the current setting will pass to the new job while pressing [Enter] or [OK] to create a new job.



To change the setting in the selected field, press [◀]/[▶]; To move between fields, press [▲]/[▼]. Alternatively, to move to the next field, press [Enter]. Create a new job automatically while pressing [Enter] in the last field.

11.1.3 Delete Jobs

STEP	OPERATION	DISPLAY
①In the job list, move the cursor to the job that you want to delete by [▲]/[▼].	[▲]/[▼]	Job Mgr.
②Confirm the job that you want to delete as right screen.		Del Job Job: RTS800 *Sure? II Abrt OK
③Press [Ent] or [OK] to delete the job. To cancel the delete operation, press [ESC] or [Abrt] and return to the previous screen.	[ENT] or [OK]	Job Mgr. * RUIDE 07-01-20 @ MQ 07-01-25 RTS800 07-01-25 SURVEY 07-01-25 New Del Ctrl Info

11.1.4 Set the Control Job

If you search for a point when a control job is specified, and the system cannot find the point in the current job, the control job is also searched. If the point is found in the control job, it is copied to the current job as a UP record.

A control job has the same format as a standard job. You can open and modify it like any other job, and you can use it to record any measured data.

STEP	OPERATION	DISPLAY
①Highlight the job that you want to use as a control job by using by [▲]/[▼].	[▲]/[▼]	Job Mgr. * RUIDE 07-01-20 @ MQ 07-01-25 RTS800 07-01-25 SURVEY 07-01-25 New Del Ctrl Info
②Press [Ctrl]. A confirmation screen appears.	[Control]	Ctrl job <on> Job: RTS800 *Set Ctrl job? Abrt OK</on>



③Press [ENT] or [OK] to confirm, otherwise cancel it by [ESC] or [Abrt] and return to the previous	[ENT] or	Job I * RUIDE MQ @ RTS800	Mgr. 07-01-20 07-01-25 07-01-25
screen. If a control job is already assigned, the newly assigned control job replaces it as the control	[OK]	SURVEY New Del	07-01-25 🗓 Ctrl Info
job. ①To clear the control job selected,		Ctrl Job <off></off>	
highlight the current control job in the job list and press the [Ctrl]		Job:	RTS800
softkey.		*Close Ctrl jo Abrt	ob? 🗓 OK

11.1.5 Display Job Information

STEP	OPERATION	DISPLAY
①Highlight the job that you want to display the information by pressing [▲]/[▼].	[▲]/[▼]	Job Mgr. * RUIDE 07-01-20 @ MQ 07-01-25 RTS800 07-01-25 SURVEY 07-01-25 New Del Ctrl Info
②The Job Info screen shows the number of records in the job while pressing [Info].	[Info]	Job Info Job: RTS800 Rec: 1 Creat: 2007-01-25

11.2 COORDINATE GEOMETRY (COGO) CALCULATIONS.

In the screen press [2] to show the menu, or access this menu from any observation or PT input screen.

11.2.1 Inverse Calculating

11.2.1.1 Inverse PT-PT

Calculating angle and distance between two coordinates: PT-PT calculates the distance and the angle between two input points.



STEP	OPERATION	DISPLAY
①In the [Menu], press [2] or ([▼]+[Enter]).	[2]	Menu————————————————————————————————————
②Display the Cogo menu.		Cogo P2 1. Inverse 2. AZ&Dist 3. Area 4. LineOff. InputXYZ
③Press [1] entering PT-PT menu.	[1]	P2 1. PT-PT 2. 3PT Ang.
	[1]	P1: 1 P2: 1 Meas Data List Stac
⑤Input the name of P1. The way to input: A: Input a point name which exists in the memory. The system calls it up automatically.	Input P1	A: N:
B: The system requests to enter the information of the point if the point doesn't exist. It will return after the point is recorded.		B: N:
C: If you press [ENT] without entering a point name, a coordinate input screen appears, and you can enter coordinates. These coordinates are not stored to the database.		C: N:

RUIDE

D:		D:
By pressing [MSR], as the D graph shows. Press [MSR1] or [MSR2] to measure a point as the first point of the line. E:		HA# 32°05′34″ VA# 22°26′25″ SD# HT: 1,000 m *Sight Press [MSR] HT OK E:
Press [list] to use the point in the memory. To select the point, use the [▲], [▼] key and [ENT] key. If the ▲or ▼ appears in the list, turn page by [◀]/[▶] key.		MP,1, MP,2 CP.4 CP.5 CP,6 SS,7,5841 ▼
F: Call up the point by [Stac].		MP,1, MP,2 CP,4 CP,5 CP,6 SS,7,5841
⑥Input the name of P2.	Input P2	P1: 1 1 P2: Meas Data List Stace
The azimuth, horizontal distance, and vertical distance from the first point to the second point are displayed. Press [Dsp] to switch		PT-PT 1/2 AZ: 45°00′00″ dHD: 2.818 m dVD: 2.000 m End Dsp Next Page 2:
between two pages. %1) ®To go on PT-PT, press [Next]; To		PT-PT 2/2 Gd: 1.414: 1 V%: 70.71% rSD: 3.464 m End Dsp Next



※1)Gd: Grade (HD/VD)

V%: 100/Gd

rSD: Slope distance PT1 to PT2

11.2.1.2 3PT Angle

The 3pt angle calculates the angle between two lines defined by three points. PT1 is the base point. Two lines are to be defined by P2 and P3, both from P1.

STEP	OPERATION	DISPLAY
①Press [2] or select [3Pt Angle]in the Inverse menu.	[2]	P2 1. PT-PT 2. 3PT-Angle
②Input the name of base point P1, and press [Ent]. About the input method, see step ⑤ in "PT-PT".	Input P1	Inp basePT
③Enter the second point (P2) to define the baseline (P1-P2), and press [ENT].	Input P2	Inp dir PT
4Enter the third point (P3) to define the second line (P1-P3). Press [ENT].	Input P3	Inp dir PT
⑤Display the result of the 3PT Angle. Press [Dsp] to switch between 2 pages.		3PT-Angle 1/2 AZ: 45°00′00″ HD1: 2.000 m HD2: 2.828 m End Dsp Next



	Page 2: 3PT Ang.
®To continue 3 Pt. Angle function,	
press [Next]; To quit, press [End],	
screen returns to Inverse menu.	

11.2.2 Azimuth and Distance (AZ&Dist)

Use angle and distance to calculate coordinate. There are two ways to calculate new points in AZ&Dist function.

11.2.2.1 AZ+HD

STEP	OPERATION	DISPLAY
①In Cogo menu press [2] (or [▼] + [ENT]) to enter the AZ&Dist menu.	[2]	1. Inverse 2. AZ&Dist 3. Area 4. LineOff. 5. InputXYZ
②In AZ&Dist menu press [1], choosing AZ+HD.	[1]	AZ&Dist 1. AZ+HD 2. Store
③Input point name of base PT and press [ENT]. About method to input, see "PT-PT" step ⑤.	Input P1	Input PT PT: Meas Data List Stac
④Input azimuth, horizontal distance (HD) and vertical distance (VD) then press [ENT].	Input HD, dVD	Input AZ AZ: HD: dVD:



⑤A recording point screen with the calculated coordinates appears. PT defaults to the last recorded PT + 1. Input code and press [ENT] to store the point.	N: 3.879 m E: 2.684 m Z: 4.000 m PT: 2 CD: List	□ Stac	
※1) To input120°35′05″, type 120.3505 and [ENT].			
If you do not enter a value in the dVD field, the value 0.0000 is used.			

11.2.2.2 Store

Store function calculates a new point based on the two defined points and angle, horizontal and vertical distances from the line defined by those two points.

STEP	OPERATION	DISPLAY
①In AZ&Dist menu press [2] choosing Store.	[2]	AZ&Dist
②Input the point name of P1 and press [ENT]. About method to input, see "PT-PT" step ⑤.	InputP1	Input Pl
③Input P2 and press [ENT].	Input P2	Input P2
④Enter the plus-minus angle, horizontal distance, and vertical distance from the baseline defined by P1-P2.If you do not enter a value in the dVD field, the value 0.0000 is used.	Input+AZ, HD, dVD + [ENT]	Input+AZ
⑤When you press [ENT] in the dVD field, a new point is calculated. The PT name defaults to the last recorded PT + 1. Press [ENT] to record the point.		N: 0.845 m E: 1.813 m Z: 2.000 m PT: 9 CD: List Stac



 Screen returns to the point input screen. P1 (base PT) defaults to the previously recorded PT. P2 defaults to the previous P1. Enter the plus-minus angle, horizontal distance, and vertical 	Input+AZ, HD,	Input P2
distance from the baseline defined by P1-P2, press [ENT].	+ [ENT]	+AZ: HD: dVD:
®a new point is calculated. The PT name defaults to the last recorded PT + 1. Press [ENT] to record the new point.		N: 1.826 m E: 2.719 m Z: 2.000 m PT: 10 CD: List Stac
Screen returns to the point input screen. P1 (base PT) defaults to the previously recorded PT. P2 defaults to the previous P1. This function goes on like this. Press [ESC] to quit the function. ※1)		Input P2

%1) To continuously calculate a new point, enter +Ang, HD, and dVD from the previous bearing line. This is a convenient way to enter Store points.

11.2.3 Calculate Area

STEP	OPERATION	DISPLAY
①In Cogo menu press numeric key [3] (or use [▼] + [ENT]) to enter into Area calculating function.	[3]	1. Inverse 2. AZ&Dist 3. Area 4. LineOff. 1 5. InputXYZ
②Input the first point and press	Input the first	Points 000
[ENT]. In the upper right corner of	point	1
the screen, a counter indicates how	+	PT: * Proce [MFM Viow
many points you have entered.	[ENT]	* Press [MEMU] View
About method to input, see "PT-PT"		Meas List Stac
step ⑤.		



③Continue to enter points until you have defined all the points in the lot.	Input other points + [ENT]	Points 003 PT: * Press [MEMU] View Meas Calc List Stac
4 Press [Calc] to calculate the area and perimeter.Press [Unit] to switch the unit of area.Press [Next] to add points to the	[Calc]	Area: 64.000 m² Perimeter: 32.000 m Unit Next Rec.
graph. Press [Rec.] to record the area calculating results. ※1) ※1) The first and last points that you eyou must enter the points in the order	•	

11.2.4 Line and Offset

Calculate coordinates from line and offset.

STEP	OPERATION	DISPLAY
①In Cogo menu press numeric key [4] (or use [▼] + [ENT]) to enter into line and off function.	[4]	Cogo 1. Inverse 2. AZ&Dist 3. Area 4. LineOff. 1 5. InputXYZ
②Enter the base point (P1). About method to input, see "PT-PT" step ⑤.	Enter P1	InputP1
③ A: Input the AZ bearing.	InputAZ or P2	A: InputAZ or P2



		ъ
B: Skip AZ item, enter a value in P2 field to specify a azimuth bearing.		B: InputAZ or P2
④Enter the horizontal distance along the baseline (STA).※1)	Input STA	LineOff. Sta x 1
⑤Input the horizontal distance perpendicular to the line (O/S) ※2)	Input O/S	LineOff. 1 STA:
⑥Input vertical distance (dVD).	Input dVD	LineOff. d\vD 1 STA: 2.000 m O/S: 2.100 m d vD:
To calculate the coordinates of the point, press [ENT] in the dVD item. You can change the Z coordinate here.		N: 1.826 m E: 2.719 m Z: 2.000 m PT: 10 CD: 1
®To record the point, press [ENT] in the CD field. The coordinates are stored as a CC record (calculated coordinates). Line definition information and "Sta", O/S, dVD values are stored in comment (CO) records.	[ENT]	N: 1.826 m E: 2.719 m Z: 2.000 m PT: 10 CD: List Stac

[%]1) A negative value in the Sta field means the opposite direction along the defined bearing line.

 $[\]ensuremath{leph}$ 2) A negative value in the O/S field is for the left-hand side of the bearing line.



11.2.5 Input Coordinates Manually

STEP	OPERATION	DISPLAY
①In Cogo menu press key [5] (or use [▼] + [ENT]) to manually enter the XYZ coordinates.	[5]	Cogo 1. Inverse 2. AZ&Dist 3. Area 4. LineOff. 5. InputXYZ
②Enter the coordinates using the numeric keys. To move to the next field, press [ENT] or [▼] in a field.	Input coordinates + [ENT]	N:
③Press [ENT] in Z field to save the point as manually input record. The display returns to the point input screen. The default PT is incremented to the next value.	[ENT]	N: 10.000 m E: 10.000 m Z: 10.000 m PT: 10 CD: List Stac

11.3 SETTINGS

STEP	OPERATION	DISPLAY
①In [Menu], press numeric key [3] (or use [▼] + [ENT]) to enter into setting function.	[3]	Menu
②The setting menu displays. Use [▲]/[▼] + [ENT] or numeric key to select the item which needs to be set. (Here take angle setting as example.)	[1]	Settings 1. Angle 6.SO 2. Dist. 7. Unit 3. XYZ 8. Record 4. Power 9. Other
③Use [▲]/[▼] to move to items that need to change be changed.	[▲]/[▼]	<angle> VA0: Zenith Min Ang: 5" HA: Azimuth</angle>

RUIDE

④Press [►]/[◀] to change the settings, and press [ENT].	[▶ν[◀]	<angle> VA0: Zenith Min Ang: 5" HA: 0 to BS</angle>
⑤If any of these settings are changed while a job is open, a confirmation screen appears, asking you whether to close the current job.※1) Press [Abrt] to use the settings in current job and abort the change. Press [OK] to close the job in measure or record function, program will ask whether to select or create a job.		 Angle>
⑥The display returns to Settings menu.※1) About the setting of twelve items,	see"11.1.2 Creatin	1. Angle 6.SO 2.Dist. 7.Unit 3.XYZ 8.Record 4.Power 9.Other 5.Comm

In the following form, the items in "_____" can't be changed once a job is created.

Item	options	
	VAO: Zenith/Vertical/Vert±90	
	Min. Ang: 1"/5"/10"	
Angle	HA: Azimuth/0 to BS	
	When this field is set to Azimuth, the horizontal angle (HA) that is displayed and	
	recorded is in Azimuth value.	
	When this field is set to 0 to BS, HA is in HA zero to BS value.	
	Scale: Numeric value between 0.990000 and 1.010000	
	T-P cm: ON/OFF	
Dist.	SeaLevel: ON/OFF	
	C&R cm: OFF/0.14/0.200	
	Max Dist: 2000m/5000m (Select max range of laser distance measurement,	
	only for reflectorless total station.)	
	Order: NEZ/ENZ	
XYZ	Marker: NEZ/XYZ/YXZ	
	AZ 0: North/South	



	Power off: 5 min/10 min/30 min/ OFF
Power	EDM off: Now/0.1 min/0.5 min /3 min /10 min/ OFF
	Sleep: 1 min/3 min/5 min/OFF
	Mode: Ruide/Setting
	Baud: 1200/2400/4800/9600 /19200/38400/57600/115200
Comm	Data.L: 8/7
	Parity: None/Even/Odd
	Stop: 1/2
SO	Add PT: This field sets the default point number to record observed data in
	stakeout.
	Angle: DEG/GON/MIL
Unit	Dist: Meter/USA Feet/USA Inch/IntlFeet/IntlInch
Or int	Temp: °C/°F
	Press: hPa/mmHg/inHg
	Store DB: RAW+XYZ/RAW/XYZ
	This setting determines whether raw and/or coordinate data is stored when you
Record	record SS, CP, or SO records in the Basic Measurement Screen (BMS) or
	Stakeout screen.
	REC Data: MEM./COMM
	Set this item to COM to output data on the COM port. The data is not stored to
	the job file.
	XYZ Dsp: Quick/Normal/Slow/Enter
	Defines speed to move to the next screen after showing XYZ of the input PT.
	2nd Unit: Meter/USA Feet/USA Inch/IntlFeet/IntlInch/None
Other	Beep: ON/OFF
	Split ST: ON/OFF
	You can separate the point numbers of station points from other record type
	point numbers. If you set the Split ST ON, you can enter single ST number in an
	additional setting screen. Or you can press [ENT] to use default point name.
	InputCod: ALPH/NUM
	User Information: Enter your information up to 20 characters.

11.4 VIEW RECORDS

•You can view data at any time, even in an observation screen or while entering points.



11.4.1 View Raw Data

STEP	OPERATION	DISPLAY
①In [Menu] press numeric key [4] (or use [▼] + [ENT]) to enter into data function.	[Menu]	
②The data menu displays. Press numeric key [1] choosing the raw data function.	[1]	
③The raw data records show in a list. The cursor stays on the last raw data record of current job. Use [▲]/[▼] to choose the records. ※1)	[▲]/[▼]	RAW Data F1, 10,
①To see detailed information for the selected records, press [ENT]. Press [ESC] to return to the record list. ※2),※3)	[ENT]	HA: 44°59′52″ VA: 102°26′43″ SD: 3.345 m PT: 5 HT: 1.000 m Del Edit Dsp Dsp N: 54697561.386 E: 58974652.011 Z: 553.011 PT: 5 CD: RUIDE Del Edit Dsp

※1)SS: Sideshots (topo shots). All shots from the basic measurement screen are stored as SS records.

CP: Shots taken in the Angle or Repeat menus, or in the basic measurement screen. F1/F2: Face-1 /Face-2 measurements.

※2) Raw records contain "PT", "HT", "CD" and "HAVA/SD".


3) When the Store DB setting is set to RAW+XYZ, press [DSP] to switch between the screens.

•When you take more than one measurement to the same point and choose to overwrite the XYZ data, the old raw record becomes raw data only. As a result, only one SS (RAW) record keeps its corresponding SS (XYZ) record. Other SS (RAW) records to the same point no longer have coordinates available.



11.4.1.1 ST Records


ST (station) records contain "ST", "HT", "BS" and "AZ". Press [Dsp] to view XYZ coordinates.



•When you assign a new ST point name in Stn Setup > QuickStn, the coordinates of the station is recorded as (0, 0, 0).

11.4.1.2 SO Records

SO: Stakeout shots. These are shots recorded in stakeout functions. Press [DSP] to switch between the screens.



•dN/dE/dZ store the difference between the stakeout shot's actual position and its planned position.

11.4.1.3 CO (code) Records

A CO record is a comment added to the job from the system. For example, when you change the Stn-Z using the Z Coord function, or you reset the horizontal angle using the BSCheck function, the system writes a comment record.

CO,Remote BM Calc.Z=3.471 -Stn Point Updated	As the left graph shows: Recorded by comment in Z-Coord function.
Del	



CO,Temp: 26.0°C Press: 1023.0 hPa
Prism: -30mm 2007.02.03
11: 19: 00

Record of temp, pressure and prism constant (SY record), which are saved when you finish station setup.

11.4.2 Delete Raw Records

STEP	OPERATION	DISPLAY
①In the RAW Data screen, use [▲]/[▼] to highlight the record that you want to delete. (Or in data screen which appears after pressing [ENT].) Press [Del].	[▲]/[▼] + [Del]	RAW Data F1, 10, F2, 10, CP,9, V SS,5 Del Edit Srch Press [ENT]: HA: 44°59′52″ VA: 102°26′43″ SD: 3.345 m PT: 5 HT: 1.000 m Del Edit Dsp
②To delete data, press [OK] or [ENT]. Not to delete, press [CE].	[OK] or [ENT]	Delete RAW Data SS, 5, * Sure? CE OK
③The system executes the selected operation, and returns to RAW Data screen.		RAW Data ST, 3 F1, 10,



11.4.3 Edit Raw Records

STEP	OPERATION	DISPLAY
①In RAW Data screen use [▲]/[▼] to highlight the record that you want to edit. (Or in data screen which appears after pressing [ENT].) Press [Edit].	[▲]/[▼] + [Edit]	RAW Data F1, 10, F2, 10, CP,9, V SS,5 Del Edit Srch Press [ENT]: HA: 44°59′52″ VA: 102°26′43″ SD: 3.345 m PT: 5 HT: 1.000 m Del Edit Dsp
②Input the new data manually, or select data from [List] or [Stac], and then press [ENT].	Input new data + [ENT]	PT: HT: CD: *Amend & press [ENT] List Stac
③To rewrite the data, press [OK] or [ENT]. Otherwise press [CE].	[OK] or [ENT]	Edit RAW SS, 5, * Rewrite? CE OK
③Program executes the selected operation, and returns to RAW Data screen.		RAW Data F1, 10,

11.4.4 Search Raw Records

In the RAW Data screen, press Srch to access the raw data search function.

STEP	OPERATION	DISPLAY
①In RAW Data screen, press [Srch].	[Srch]	RAW Data F1, 10,



②Input the search criteria.	Search RAW Data Type: All PT:
A: To find a point by name, enter the name in the PT field and press [ENT] twice.	Search RAW Data Type: All PT:
B: You can use the wildcard (*) in	B:
PT or CD field, for example: Input	Search RAW Data Type: All
30*, you can find 300、301, 302,	PT: *
3000A, 3010, etc.	HT:*
	List Stac
C: To search by point type, press	C:
[▲] to move to the Type field and	Search RAW Data
use [<] or [>] to change the selected	Type: All PT:
point (All/ST/SS/SO/CP/CO/MLM).	HT:
※1)	
③Detailed data for the selected	RAW Data
record appears. Press [ESC] to	SS, 10,
return to the list. Press [Dsp] to	SS, 10,
change the fields shown.	SS,9, V SS,5
*2), *3)	Del Edit Srch
※1) If you select a type in the Type it	em, you do not have to enter a value in the CD item. Press [ENT]
in the PT item to start the search.	
$st\!$	the search criteria, the matching points are displayed in a list. Use
[▲]/[▼] to highlight the point you war	nt to use. Then press [ENT] to select it.
※3) If no point matches the specified	critoria "DT Not Evict" displays. Proce any koy to return to the
, , ,	citiena, Fi Not Exist displays. Fless any key to return to the

11.4.5 View Coordinates Data

In Data menu press [2: XYZ Data], then coordinate data is displayed in a list, with the newest record at the bottom of the screen. Use $[\blacktriangle]/[\blacktriangledown]$ to scroll through the records. (Use $[\blacktriangleleft]/[\blacktriangleright]$ to move up or down one page), press [ENT] to see more detailed information.

The header (XYZ, YXZ, NEZ or ENZ) depends on the Coord.



STEP	OPERATION	DISPLAY
①In Data menu press numeric key [2], choosing XYZ Data.	[2]	
②The XYZ data list is open. The cursor stays on the last coordinate record of current job. Use [▲]/[▼] to scroll through the records. ※1), ※2)	[▲]/[▼]	XYZ Data SS, 10, MP, 10, SS,9, V MP,5 Del Edit Srch Inp.
③After selecting the XYZ Data you want to view, press [ENT] to see more detailed information. Press [ESC] to return to the list.※3)	[ENT]	N: 54697561.386 E: 58974652.011 Z: 553.011 PT: 5 CD: RUIDE Del Edit

%1)UP: uploaded point coordinates

MP: manually input point coordinates

CC: points calculated in Cogo

RE: Points calculated in Resection.

SS: Sideshots, All shots from the basic measurement screen are stored as SS records.

**2) When the Store DB setting is set to RAW+XYZ" or "XYZ", shots in the basic measurement screen (SS records), in various O/S functions (SS records), in 2Pt.Ref. L and Ref.Arc in PRG (SS records) and in some Stakeout functions (SO records) store coordinate records as well. The format of the data is the same as other coordinate records.

※3) All coordinate records contain "N/E/Z", "PT" and "CD" fields.

11.4.6 Delet Coordinate Records

STEP	OPERATION	DISPLAY	
①In XYZ Data screen, use [▲]/[▼] to highlight the record that you want to delete. (Or in data screen which appears after pressing [ENT]), press [Del].	[▲]/[▼] + [Del]	XYZ Data SS, 10, MP, 10, SS,9, V MP,5 Del Edit Srch In Press [ENT]: HA: 44°59′52″ VA: 102°26′43″ SD: 3.345 m PT: 5 HT: 1.000 m Del Edit Dsp	▲ Î



②To delete data, press [OK] or [ENT]. Not to delete, press [CE].	[OK] or [ENT]	Delete XYZ SS, 5, * Sure? CE OK
③The system executes the selected operation, and returns to XYZ Data screen.		XYZ Data SS, 10, MP, 10, SS,9, V MP,15 Del Edit Srch Inp.

11.4.7 Edit Coordinate Data

STEP	OPERATION	DISPLAY		
①In XYZ Data screen, use [▲]/[▼] to highlight the record that you want to edit. (Or in data screen which appears after pressing [ENT]), press [Edit].	[▲]/[▼] + [ENT]	XYZ Data SS, 10, MP, 10, SS,9, V MP,5 Del Edit Srch Press [ENT]: N: 54697561,386 E: 58974652,011 Z: 553,011 PT: 5 CD: RUIDE Del Edit	•	
②You can edit PT, CD and coordinate data. Input the new data manually, and press [ENT].	Input new data + [ENT]	N:		
③After editing data, press [ENT] in CD field, the program displays as the right graph. To rewrite the data, press [OK] or [ENT]. Otherwise press [CE].※1) ※1) You cannot edit the coordinate re	[ENT]	EditXYZ MP, 5, * Rewrite? CE OK nt station.	Ô	

%1) You cannot edit the coordinate records of the current station.%2) You can't edit the coordinate record from measurement (SS record).



11.4.8 Search Coordinate Records

Press [Srch] to access the XYZ data search function.

STEP	OPERATION	DISPLAY
①In XYZ Data screen, Press [Srch].	[Srch]	XYZ Data SS, 10, MP, 10, SS,9, V MP,5 Del Edit Srch Inp.
②Input the search criteria. A:		Search XYZ Type: All PT: CD: List Stac
To find a point by name, enter the name in the PT field and press [ENT] twice.		Search XYZ Type: All PT:
B: You can use the wildcard. (*) in PT or CD field, for example: Input 30*, you can find 300, 301, 302, 3000A, 3010, etc.		Search XYZ Type: All
C: To search by point type, press [▲] to move to the Type field and use [<] or [>] to change the selected point (All/MP/UP/CC/RE).		Search XYZ Type: All PT: CD:
③If more than one point matches the search criteria, the matching points are displayed in a list. Use [^] or [v] to highlight the point you want to use. Press [ENT] to select it. Detailed data for the selected record appears. Press [ESC] to return to the list. ※1) If no point matches the specified		XYZ Data SS, 10, MP, 10, SS,9, V MP,5 Del Edit Srch Inp.



11.4.9 Enter Coordinates

STEP	OPERATION	DISPLAY
①In XYZ Data menu, press [Input].	[Input]	XYZ Data SS, 10,
②A new input point screen. Displays. The PT field defaults to the last recorded PT + 1, but you can change the value shown. Enter the coordinates and the PT and CD and then press [ENT]. When you press [ENT] in the CD field, the point is stored as an MP record.	Input new data + [ENT]	N:
③After you have recording a point, the next point input screen is shown with the updated default You can record NE, NEZ, or Z data to the database.		N:

11.4.10 ViewRecords by Station

STEP	OPERATION	DISPLAY
①In Data menu press numeric key [3] to select ST→SS/SO/CP.	[3]	
②Station Data list shows. Use [▲]/[▼] to scroll through the records.	[▲]/[▼]	Stn Data ST, 10, ST, 15, ST,19, ST,20 Del Edit Srch
③After selecting the Data you want to view, press [ENT] see more detailed information. Press [ESC] to return to the list.	[ENT]	ST: 19 HI: 1.600 m BS: 20 AZ: 0°00′00″ * Press [ENT] View Del Edit Dsp



				RAW	Data	
④Press [ENT] again display all the observation data from the selected station. ※1)	[ENT]		SS, 10, SS, 10, SS,9, V SS,5			ů
			Del	Edit	Srch	
※1) For detailed information about each point type and format, see "11.4.1 Viewing Raw Data".						

11.4.11 Delete Station Records

•When you delete a ST record, all the observation data from the station is also deleted.

STEP	OPERATION	DISPLAY
①In Stn Data list, use [▲]/[▼] to highlight the record that you want to delete. (Or in data screen which appears after pressing [ENT]), press [Del].	[▲]/[▼] + [Del]	Stn Data ST, 10, ST, 15, ST,19, ST,20 Del Edit Srch Press[ENT]: ST: 19 HI: 1.600 m BS: 20 AZ: 0°00′00″ * Press [ENT] View Del Edit Dsp
②To delete data, press [OK] or [ENT]. Not to delete, press [CE].	[OK] or [ENT]	Delete RAW Data ST, 19, * Sure? CE OK
③If you press [ENT], a confirming dialog box appears. To delete all data of this station, press [OK] or [ENT]. Not to delete, press [CE].	[OK] Or [ENT]	Delete Str ! Delete all SS/SO /CP of this STN * Sure? CE OK



11.4.12 Edit Station Records

The system will not recalculate the measurements if you change the station record.

STEP	OPERATION	DISPLAY
①In Stn Data list, use [▲]/[▼] to highlight the record that you want to edit. (Or in data screen which appears after pressing [ENT].) Press [Edit].	[▲]/[▼] + [Edit]	Stn Data ST, 10, ST, 15, ST,19, ST,20 Del Edit Srch Press [ENT]: ST: 19 HI: 1.600 m BS: 20 AZ: 0°00′00″ * Press [ENT] View Del Edit Dsp
②Program displays as the right graph. Input the new data manually, or select data from [List] or [Stac], and then press [ENT].※1)	Input new data + [ENT]	ST:
③To rewrite the data, press [OK] or [ENT]. Otherwise press [CE].	[OK] or [ENT]	Edit RAW ST, 19, * Rewrite? CE OK
③The system executes the selected operation, and returns to RAW Data screen.※1) You can't edit the current station.		Stn Data ST, 10, ST, 15, ST,19, ST,20 Del Edit Srch

- •If you change the station or instrument height (HT) values, the coordinates of observation points are not recalculated.
- •If you change the BS or AZ values, raw records are not recalculated.



11.4.13 Search Station Records

STEP	OPERATION	DISPLAY
①In Stn Data list, press [Srch].	[Srch]	Stn Data ST, 10, ST, 15, ST,19, ST,20 Del Edit Srch
②Input the search criteria.A:To find a point by name, enter the		Search Stn Type: ST PT: CD: List Stac
name in the PT field and press [ENT] twice.		A: Search Stn Type: ST PT: 9 CD: List Stac
B: You can use the wildcard. (*) in PT or CD field, for example: Input 30*, you can find 300, 301, 302, 3000A, 3010, etc.		B: Search Stn Type: ST * CD: * List Stac
③If more than one point matches the search criteria, the matching points are displayed in a list. Use [^] or [v] to highlight the point you want		Stn Data ST, 10 ST, 10
to use. Press [ENT] to select it. Detailed data for the selected record appears. Press [ESC] to return to the list. **1) If no point matches the specified.	criteria. an error so	Del Edit Srch

11.4.14 Point Name List and Code List

The instrument stores two list files: a list of PT names and a list of CD names. The structure and functionality of these files is the same, i.e. Delete, Edit, Add points/codes and layer.

The PT name list is useful if you have to handle more than one pattern of point names. For example, you may need to use points named PT=1, 2, 3 as well as



PT=C1, C2, C3

The code list is a list of feature codes. You can use it to store your own codes.

11.4.14.1 Delete Points/Codes

STEP	OPERATION	DISPLAY
①In Data menu, press numeric key [4] to open PT list.	[4]	
②The point list is shown. Use 3 softkeys to customize the list.		1 2 3 4 5 Del Edit Add
③In PT List use [▲]/[▼] to select the points/ codes you want to delete, and press [Del].	[▲]/[▼] + [ENT]	1 2 3 4 5 Del Edit Add
(4) A confirmation screen appears. Press [ENT] or [OK] to delete the item. Press [CE] to cancel the deletion.	[OK] Or [ENT]	Delete PT: 1 * Sure? CE OK

11.4.14.2 Edit Points/Codes

STEP	OPERATION	DISPLAY
①In the PT List use [▲]/[▼] to select the points/ codes you want to edit, and press [Edit].	[▲]/[▼] + [Edit]	1 2 3 4 5 Del Edit Add
②Input new point name/code, and press [ENT].	Input PT/Code + [ENT]	PT:* Max 16 char



③ A confirmation screen appears.		Edit		
Press [ENT] or [OK] to accept the	[ENT]			
changes and update the list.	or	→RUIDE		
Press [CE] to cancel editing.	[OK]		* Rewrite?	Û
		CE		OK

11.4.14.3 Add a Point Name

STEP	OPERATION	DISPLAY
①In the point list, press [Add].	[Add]	1 2 3 4 5 Del Edit Add
②Input the PT name, press [ENT].	Input point name + [ENT]	Add PT: *Max 16 char
③The added point appears in the point list.※1)		2 3 4 5 RUIDE Del Edit Add
※1) You can store up to 256 points.		


11.4.14.4 Add a Code

STEP	OPERATION	DISPLAY
①In the Code List press [Add].	[Add]	FANGJIA LUDING XIEPO GONGLU Del Edit Add
②Enter the serial number in the CD		Add
field. Input code content in Rec	Input CD and	CD: 105 1
field. If you leave the REC field	content	(Rec: RUIDE)
blank, the CD value is stored. After	+	* REC=text rec
inputting, press [ENT]. %1), %2)	[ENT]	(If code not match)

136



 $\ensuremath{\Im}$ The added code appears in the code list. $\ensuremath{\Im}$ 3)



※1) The Rec. field is optional, when you need to save a corresponding code to every serial number, you can input the code content in this field. For example if you input"12" in "CD" field, and input "RUIDE" in "Rec", it means you input RUIDE as a code, with the serial number 12. In Quick Code function you can input serial number (CD) to call up code.


(*2) To save the code same as the one in the CD field, leave the Rec field blank and press [ENT].(*3) You can store up to 256 codes.

11.5 COMMUNICATION


11.5.1 Download Data

Connect the instrument to the PC with communication cable. Install the driver of the cable if necessary. Run the data transfer software.


a. Frist, make the communication settings in accordance with that of the total station. Select the menu "COM" and click "Option" as follow.








b. Click "COM" and then "Download".







Then the system requests to confirm if you are ready to transfer the data.

Caution: before you click "OK" and start the transfer, make sure you have made the following operation on the total station.

STEP	OPERATION	DISPLAY
①In Menu, Press [5] or [▼] + [Enter] to display the Communication menu.	[5]	1.Job 6.1 Sec. 2.Cogo 7.Ajustt 3.Set 8.Time 4.Data 9.Format 5. Comm 10.Info
②Choose [1] to transfer the date through the RS232 cable. ※1), ※2)	[1]	1. From RS232 2. From USB 3. Import/Export SD
③Select [1. SendData].	[1]	1.SendData 2.LoadData 3.PT List 4.Cod List

RUIDE

A: Press [Job], and then [▲]/[▼] to select the jobs from which the data is going to be downloaded. Press [ENT] to return. B: To set the communication parameter, press [Comm]. To select item, press [▲]/[▼], To select option, press [◀]/[▶]; Press [ENT] to return after the setting.		SendData Job: RUIDE Frmt: SDR33 Data: RAW Data Job
⑤Set the format of the data. Press [¶] [▶] to select the format of the data to transfer to, and press [ENT] to confirm. The data forms: RUIDE/SDR33.	[◀Ŋ[▶] + [ENT]	SendData Job: RUIDE Frmt: RUIDE Data: RAW Data Job Comm
⑥To select the format of the transferred data, press [◀]/[▶] and [ENT]. The types of the data: RAW Data /XYZ Data	[◀)/[▶] + [ENT]	SendData Job: RUIDE Frmt: RUIDE Data: RAW Data Job Comm
Press "OK" on the communication software on your computer.Press [Strt] to send the data.	[Strt]	Link cable Job: RUIDE Send Rec: * Open Xon/Xoff Abrt Strt
®To stop the transfer, press the [Stop]. The system will return to the menu of [Comm] after the transmission.		Link cable Job: RUIDE Send Rec: 2 * Open Xon/Xoff Stop




- ※1) RTS-820R³ series is supportable to mini USB port and SD card.
- ※2) It is a must to install the cable driver if you use a multi-port cable (RS232 and mini USB intergrated).

11.5.2 Upload the Coordinate Data


Connect the total station to the PC with communication cable, and set the communication settings in accordance with that of the total station.

First, open the file you want to upload to the total station. This file can be the file generated by the software, also it can be a text file.





Clisk "COM" and then "Upload".



The system asks for a confirmation to start the transfer. Before you click OK to transfer, you should operate the following procedure.



STEP	OPERATION	DISPLAY
①In the Comm menu, press [2. Load Data].	[2]	1.Send Data 2.Load Data 3.PT List 4.Code List
②※1) A: As shown in the right graph, press Job and then [▲]/[▼] to select the one to load data, and press [ENT] to return B: Set Comm parameter by pressing [Comm]. To change other item, press [▲]/[▼]. It should be the same as that of the communication		Load Data Job: RUIDE Frmt: PT/N/E/Z/CD * Open Xon/Xoff Job
software. To change the option of the item, press [] [] Press [Enter] to return. C: The default data format is displayed. To change the order of data fields, press the Edit softkey. Use [] [] to select Job and then [] to change. After setting, press [Save] or [ENT] to return. 3After all setting, press [OK] or [ENT], a dialog as the right graph shows. Press [Strt] and then click OK on the communication software on your computer to send data from PC to the total station.	[OK] or [Enter]	C: Press [Edit] Receive XYZ format PT N E Z CD * Change Use



①To stop sending, press [Stop]. After sending data, program returns to [Comm] menu automatically. ※2)		Link cable Job: Rec:	RUIDE 2	
※1)In the terminal program, set flow or	control to Xon/Xoff.	Бюр		L
※2) As each point is received by the i		in the Recor	ds field is increased.	

11.5.3 Upload a PT List or Code List

Connect the instrument to the PC with communication cable, and run the communication software on PC. Open the PT List file you want to upload and click "COM" and then "Upload". The procedures are similar to the previous operations. And before transfer, operation the total station as follow.

STEP	OPERATION	DISPLAY
①In the Comm menu, select [3. PT List].	[PT list]	1.Send Data 2.Load Data 3.PT List 4.Code List
②Press [Comm] to set communication parameter, make sure the setting of the total station is consistent with the communication software. After setting, press [Strt] and click "OK" to start to transfer. To cancel sending, press [Abrt].		Current list Will be Rewritten! Abrt Comm Strt
③Start data sending. To stop transferring, press [Stop]. After sending data, program returns to [Comm] menu automatically.		PT List 10 Stop

- •The uploaded PT /Cod List will always replace the primary PT/Cod List in the total station.
 - •You can store up to 256 codes or point names.



11.6 1 SEC-KEYS

1 Sec.Keys are the functions that when you hold down a certain key for 1 second, the setting of this key will be activated.

In the menu, press [6] to enter into the setting of [MSR], [Disp], [User], [SO] and [Data] keys.

11.6.1 [Meas] Kev Setting

11.6.1 [Meas] Key Setting		
STEP	OPERATION	DISPLAY
①In [Menu], press numeric key [6](or use [▼]+[ENT]) to enter into 1 Sec. key setting.	[6]	Menu
②In 1Sec.Key menu, press [1] to enter [MSR] setting.	[1]	1Sec. key
③There are two [MSR] keys, corresponding to [MSR1] and [MSR2] keys under the screen. Each key has its own setting, select the MSR keys which need to set meas mode. Then press [ENT] (or press numeric key [1] or [2] directly.)	[1] or [2]	Meas Mode 1. Meas 1 2. Meas 2
④Each [MSR] key has 4 settings. In the "Const" item, use numeric keys to input values. In the other items, use [▶]/[◀] to change the settings. ※1)	[▶]/[◀] + [▲]/[▼]	<meas1> TGT: Prism Const: -30mm Mode: Fine [s] Rec: All</meas1>
⑤After setting, press [ENT] to return to 1 Sec.Key menu.	[ENT]	1Sec. key 1.[Meas] >>Set 2.[Disp] Meas 1/2 3.[User] Meas Para 4.[SO] 5.[Data] g down [MSR1] or [MSR2] for one second.



11.6.2 [DISP] Key Settings

To change the display items in the basic measurement screen, and in SO observation screen, press [2. Disp] in the 1Sec. key menu.

STEP	OPERATION	DISPLAY
①In 1 Sec. key menu, press [2] to enter into [Disp] setting.	[2]	
②To move the cursor, use [▶]/[◀], [▲]/[▼]. To change the display item, press	[▶ N[◀]	CDISP1> CDISP2> CDISP3> HA AZ HIL VA HID V% SD VD Z
③The sceen returns to 1Sec.key menu.※1) You can also access the Disp set		1Sec.key 1.[Meas] 2.[Disp] >>Change 3.[Data] Display 4.[SO] Meas&SO 5.[Data]

11.6.3 [User] Key Settings

STEP	OPERATION	DISPLAY
①In 1 Sec. Key menu, press [3] to enter into [User] setting.	[3]	1.[Meas] 2.[Disp]
②There are two [USR] keys. The function that is assigned to each key is displayed beside the key name. Press [1] to enter into [User1] setting. (Here take User1 as example.) ※1)	[1] or [2]	User Key 1. User1 <offset> 2. User2<input ht=""/></offset>



②Use [▲]/[▼] to select the expecting function, and then press [ENT]. ※2) If an item on the list has an arrow "→" beside, and if you select this item, the whole menu is assigned to the [USR] key. To assign a specific function from the sub-menu, press [▲]/[▼] to highlight the function. Then press [ENT].	[▲]/[▼] + [ENT]	【User1】 Input HT BS Check TGT Cogo→ *Offset→ 【Cogo (Menu】 Inverse→ AZ&Dist→ Area LineOff. InputXYZ
③After setting, press [ENT] to return to 1Sec.Key menu.	[ENT]	1Sec.key 1.[Meas] 2.[Disp]
※1) You can also access the User settings screen by holding down [USR] for one second.※2) The asterisk (*) indicates the function that is currently assigned to the key.		

11.6.4 [SO] Key Settings


STEP	OPERATION	DISPLAY
①In 1 Sec. Key menu, press [4] to enter into [SO] setting.	[4]	1.[Meas] 2.[Disp] >>Set 3.[User] Add Pt 4.[SO] SO PT 5.[Data]
②Input added value of Stake-out point and press [ENT].	Input added value of PT + [ENT]	<s-o> Add PT: 0</s-o>
3The display returns to 1Sec.Key menu.		1.[Meas] 2.[Disp] >>Set 3.[User] Add Pt 4.[SO] SO PT 5.[Data]



11.6.5 [Data] Key Settings

STEP	OPERATION	DISPLAY
①In 1 Sec. Key menu, press [5] to enter into [Data] setting.	[5]	1Sec.key 1.[Meas] 2.[Disp]
②The asterisk (*) indicates the currently selected view format.		【Data type】 *1.RAW Data 2.XYZ Data 3.ST→SS/SO/CP
③To move the cursor, use [▲]/[▼] and then [ENT] to confirm. Press [Data] again, the set Data type will display.	[▲]/[▼] + [ENT]	【Data type】 1.RAW Data * 2.XYZ Data 3.ST→SS/SO/CP
The display returns to 1Sec.Key menu.		1Sec.key 1.[Meas] 2.[Disp] >>Set 3.[User] Data Type 4.[SO] [DAT]Key 5.[Data]

11.7 DATE AND TIME



In [Menu], select [8. Time] to enter into setting the Date & Time screen.

Date

Enter the date in Year-Month-Day format.

For example, to change the date to Jan. 2, 2007, input:

To move to the Time item, press [ENT] in the Date item.

Time

Enter the time in 24-hour format. The inputting method is same as inputting Date.



Press [ESC] to cancel the input.

11.8 FORMAT

Format

1. Delete All Datas
2. Delete All Job
3. Initialization

Delete All Datas: Delete all data in the memory, with the jobs and job settings

unchanged.

Delete All Job: Delete all files in the memory.

Initialization: Delete all data and files, and return to initial setting.

11.9 INFORMATION

Information of instrument type, number and version are displayed.

Type:

RTS820R3 (for instance)

Number

Serial number of the plant.

Ver.

On-board software version may differs from time to time.


HVer: version of the angle measurement system SVer: verison of the distane measurement system




12. CHECK AND ADJUSTMENT

This instrument has undergone a strict process of checking and adjustment, which ensures that it meets quality requirement. However, after long periods of transport or under a changing environment, there may be some influences on the internal structure. Therefore, before the instrument is used for the first time, or before precise surveys, user should launch check and adjustment introduced in this chapter to ensure the precision of the job.

12.1 PLATE VIAL





Check

Please refer to Chapter 3.2 "Leveling by Using Plate Vial"

Adjust

- 1. Adjust leveling screws, make plate bubble centered;
- 2. Rotate the instrument 180°; watch the offset of plate level;
- 3. Tweak adjustment screws (on the right of the plate vial) with the correction pin to make plate bubble to move half of the offset back;
- 4. Rotate the instrument 180°, check adjustment result;
- 5. Repeat the steps above until the plate level is centered in all directions.

12.2 CIRCULAR VIAL

Check

No adjustment is required if the bubble of circular vial is in the center after checking and adjustment of the plate vial.

Adjust

- 1. Adjust circular bubble after plate bubble is centered.
- 2.Loosen the screw (one or two) opposite with bubble deflective direction:
- 3. Tighten the screw on the direction accordant deflective until circular bubble is centered;




- 4.Adjust three adjustment screws for several times until circular bubble is centered;
- 5. The force power fixing three adjustment screws must be consistent when circular level is centered at last.

12.3 INCLINATION OF RETICLE

Check


- 1. Sight object A through the telescope and lock the horizontal and vertical clamp screws.
- 2. Move object A to the edge of the field of view with the vertical tangent screw (point A').
- 3. Adjustment is not necessary if object A moves along the vertical line of the reticle and point A' still in the vertical line.

As illustrated, A'offsets from the center to the cross hair tilts, then need to adjust the reticle.



Adjust

- 1. If the object A does not move along with the vertical line, firstly remove the eyepiece cover to expose the three or four reticle adjusting screws.
- 2. Loosen all the reticle adjusting screws uniformly with an adjusting pin. Rotate the reticle around the sight line and align the vertical line of the reticle with pointA'.
- 3. Tighten the reticle adjusting screws uniformly. Repeat the inspection and adjustment to see if the adjustment is correct.
- 4. Replace the eyepiece cover.





12.4 PERPENDICULARITY BETWEEN LINE OF SIGHT AND HORIZONTAL AXIS (2C)

Check

- 1. Set object A at about 100 meters away the same height as the instrument, and make the vertical angle with $\pm 3^{\circ}$. Then level and center the instrument and turn on the power
- 2. Sight object A in Facel and read the horizontal angle value. (e.g.: Horizontal angle $L=10^{\circ}13'10''$).
- 3. Loosen the vertical and horizontal clamp screws and rotate the telescope. Sight object A in Face II and read the horizontal angle value. (e.g.: Horizontal angle $R=190^{\circ}13'40''$).
- 4. 2 C=L-R±180°=-30"≥± 2 0 ", adjustment is necessary.

Adjust

A. Electronic Adjustment Operation Steps:

STEP	OPERATION	DISPLAY
①After leveling the instrument, press [MENU] to enter into the menu, press [7] (or [▼] + [ENT]) to enter Adjustments.	[MENU] + [7]	
②In Adjustment press "2. Collimation".	[2]	
③In Face I precisely collimate the target, and press [OK].	Collimate the target + [OK]	Collimation HA# 24 15'00" OK
4)The System indicates "Turn to F2". Rotate the telescope, and collimate the same target precisely in Face, press [OK].	Sight the target in reverse position + [OK]	Collimation HA# 204°15′22″ OK



⑤After setting, the screen displays "set", and returns to Adjustment menu automatically.


----Adjustments -----

1.VO Adjustments
2.Collimation

3.Inst. Constant 4.VADJ Set

5.VO/Axis const.

Ô



- B. Optics Adjustment (professional maintenance man only)
- 1. Use the tangent screw to adjust the horizontal angle to the right reading which has been eliminated C, R+C=190°13′40″-15″=190°13′25″
- 2. Take off the cover of the reticle between the eyepiece and focusing screw. Adjust the left and right adjusting screws by loosening one and tightening the other. Move the reticle to sight object A exactly.
- 3. Repeat inspection and adjustment until $\mid 2 \text{ C} \mid < 2 \text{ 0}$ ".
- 4. Replace the cover of the reticle.

Note: After adjustment, need to check the photoelectricity coaxiality.

12.5 VERTICAL INDEX DIFFERENCE COMPENSATION

Check

- 1. Mount and level the instrument and make the telescope parallel with the line connecting the center of the instrument to any one of the screws. Lock the horizontal clamp screw.
- 2. After turning on the power, zero the vertical index. Lock the vertical clamp screw and the instrument should display the vertical angle value.
- 3. Rotate the vertical clamp screw slowly in either direction about 10mm in circumference, and the error message "b" will appear. The vertical axis inclination has exceeded 3 ´ at this time and exceeds the designated compensation range.
- 4. Rotate the above screw to its original position, and the instrument display screen will show the vertical angle again, meaning that the vertical index difference compensation function is working.

<u>Adjust</u>

If the compensation function is not working, send the instrument back to the factory for repair.



12.6 ADJUSTMENT OF VERTICAL INDEX DIFFERENCE (I ANGLE) & SETTING VERTICAL INDEX O

Inspect the item after finishing the inspection and adjustment of items in 12.3 and 12.5.

Check

- 1. Power on after leveling the instrument. Collimate object A in Face I and read the Vertical angle value L.
- 2. Rotate the telescope. Sight object B in Face $\,\mathrm{II}\,$ and read the Vertical angle value R.
- 3. If the vertical angle is 0° in zenith, $i=(L+R-3\ 6\ 0\ °)\ /\ 2$ If the vertical angle is 0° in horizon. $i=(L+R-1\ 8\ 0\ °)\ /\ 2$ or $(L+R-5\ 4\ 0\ °)\ /\ 2$.
- 4. If $|i| \ge 1$ 0" should set the Vertical Angle 0 Datum again.

Adjust

STEP	OPERATION	DISPLAY
①In Adjustments press "1. V0 Adjustments".	[1]	Adjustments 1.VO Adjustments 2.Collimation 3.Inst. Constant 4.VADJ Set
	Collimate the	VO Adjustments
②In Face I, precisely collimate	target	X: -0°00′21″
target and press [OK].	+	VA: 94°25′39″
	[OK]	
		OK
	Collimate the	VO Adjustments
③System prompt "Turn to F2".	prism in	X: 0°00′06″
Rotate the telescope, and collimate	reverse	VA: 265°34′05″
the same target precisely in Face ${ m II}$.	position	
Press [OK].	+	OK
	[OK]	
(4) The setting is finished, screen		
displays "Set", and turns back to		
Adjustments automatically.		

Note:

1. Repeat the checking steps to measure the Index Difference (i angle). If the Index Difference cannot meet the requirement, user should check whether the three steps



of the adjustment and the collimation are right. Then set again according to the requirement.


2. If Index Difference still not meets the requirement after the repeated operation, the instrument should be returned to factory for inspection and repair.

12.7 OPTICAL PLUMMET

Check

- 1. Set the instrument on the tripod and place a piece of white paper with two crisscross lines on it right below the instrument.
- 2. Adjust the focus of the optical plummet and move the paper so that the intersection point of the lines on the paper comes to the center of the field of view.
- 3. Adjust the leveling screws so that the center mark of the optical plummet coincides with the intersection point of the cross on the paper.
- 4. Rotate the instrument around the vertical axis, and observe whether the center mark position coincides with the intersection point of the cross at every 90°.
- 5. If the center mark always coincides with intersection point, no adjustment is necessary.

Otherwise, the following adjustment is required.



Adjust

- 1. Take off the protective cover between the optical plummet eyepiece and focusing knob.
- 2. Fix the paper. Rotate the instrument and mark the point of the center of optical plummet which falls on the paper at every 90°. As illustrated: Point A, B, C, and D.
- 3. Draw lines that attach AC and BD and mark the intersection point of the two lines as O.
- 4. Adjust the four adjusting screws of the optical plummet with an adjusting pin until the center mark coincides with Point O.
- 5. Repeat the inspection and adjusting steps to make the instrument meets the requirements.
- Replace the protective cover.



12.8 INSTRUMENT CONSTANT (K)


Instrument constant has been checked up and adjusted in the factory, K=0. It seldom changes and it is suggested to check one or two times every year. The inspection should be made on the base line, also can be made according to the following method.

Check

- 1. Mount and level the instrument on Point A at a plain field. Use the vertical hair to mark Point B and Point C with the distance of 50m on the same line, and set the reflector accurately.
- 2. After setting temperature and air pressure, measure the horizontal distance of AB and AC accurately.
- 3. Set the instrument on Point B and center it accurately, measure the Horizontal Distance of BC accurately.
- 4. Then the Instrument Constant can be obtained:

$$K=AC-(AB+BC)$$

K should be near to 0, If \mid K \mid >5mm, the instrument should be strictly inspected in the standard baseline site, and adjusted according to the inspection value.



<u>Adjust</u>

If a strict inspection proves that the Instrument Constant K has changed and is not close to 0. If the operator wants to adjust, should set Stadia Constant according to the Constant K


- •Set the orientation via the Vertical Hair to maintain Point A, B, C on the same line precisely. There must be a fixed and clear centering mark on the ground of Point B
- •Whether the prism center of Point B coincides with the Instrument Center is a significant step to inspect the accuracy. So on Point B the tripod or compatible tribrach should be used. It will decrease the difference.



Input Instrument Constant:

STEP	OPERATION	DISPLAY
①In Adjustments menu press "3. Inst. Constant"。	[3]	Adjustments 1.VO Adjustments 2.Collimation 3.Inst. Constant 4.VADJ Set
②Input the constant, and press [OK] or [Enter]. If not input, press [Abrt].	Input constant + [OK]	Inst. Constant Const: 0.0 mm Abrt OK
③ Screen turns back to Adjustments menu.		Adjustments 1.VO Adjustments 2.Collimation 3.Inst. Constant 4.VADJ Set

12.9 PARALLEL BETWEEN LINE OF SIGHT AND EMITTING PHOTOELECTRIC AXIS



Check

- 1. Set the reflector 50m away from the instrument.
- 2. Collimate the center of the reflector prism with reticle.
- 3. Switch on the instrument, and enter into Distance Measurement Mode. Press [DIST] (or [All]) to measure. Rotate the Horizontal Tangent Screw and Vertical Tangent Screw to launch electric collimation and make the light path of EDM unblocked. In the bright zone find the center of emitting photoelectric axis.
- 4. Check the center of reticle to coincide with the center of emitting photoelectric axis. If so, the instrument is proved eligible.

<u>Adjust</u>

If the center of reticle deviates from the center of emitting photoelectric axis, user should send the instrument to professional repair department.



12.10 TRIBRACH LEVELING SCREW

If the leveling screw appears flexible, adjust the two adjusting screw in the leveling screw to tighten the screw appropriately.

12.11 RELATED PARTS FOR REFLECTOR

1. The Tribrach and Adapter for Reflector

The plate vial and optical plummet in the adapter and tribrach should be checked. Refer to Chapter 10.1 and 10.8. for more information.

2. Perpendicularity of the prism pole

As illustrated in Chapter 10.8, mark '+' on Point C, place the tine of the prism pole on the Point C and do not move during the inspection. Place the two feet tine of Bipod on the cross lines of Point E and F. Adjust the two legs "e' and "f" to make the bubble on the prism pole centered.

Set and level the instrument on Point A near the cross. Sight the tine of Point C with the center of reticle, and fix the Horizontal Clamp Screw. Rotate the telescope upward to make D near the horizontal hair. Flex the prism pole Leg "e" to make the D in the center of reticle. Then both Point C and D are on the central line of reticle.

Set the instrument on Point B to another cross lines. With the same way to flex the Leg "f" to make Point C and D on the central line of reticle.

Through the adjustment of the instrument on Point A and B, prism pole has been perpendicular. If the bubble offsets from the center, adjust the three screws under circular vial to make the bubble centered.

Check and adjust again until the bubble is in the center of the vial from both directions of the prism pole.



13. SPECIFICATION

RTS-820 series

MODEL	RTS-822/825	RTS-822R/825R	RTS-822L/825L	RTS-822R ³ /825R ³
telescope				
Image	Erect			
Telescope Length		152	2 mm	
Effective Aperture		,	ce Meter: 47 mm)	
Resolving Power			3"	
Magnification			60×	
Field of view		1'	°30′	
Minimum focus			.3m	
Stadia Ratio		1	00	
Stadia Accuracy		≦0	.4%D	
angle measurement	t	1		
Measuring Method	Incremental	Incremental	Absolute	Absolute
	Photoelectronic	Photoelectronic	Encoding	Encoding
Diameter of		79)mm	
raster disk				
Minimum Reading			electable	
Accuracy			optional	
Detection method	Horizontal: Dual Vertical: Dual			
Measuring Unit	360°/400Gon/6400Mil selectable			
Vertical angle 0°		0°in zenith / 0°in	horizon selectable	
distance measurement				
Single prism (in fine	1.0km	5.0km	5.0km	5.0km
weather condition)	1.01411	0.01111	0.01411	0.01411
Triple prism (in fair	2.5km	7.0km	7.0km	7.0km
weather condition)			7.10.4.1	
Reflectorless Mode	-	200m	-	300m
Display	Max: 99999999999999 m Min: 1 mm			
Unit	Meter/US feet/US inch/International feet/International inch			
Precision	±(2+2×10-6·D)mm			
Measuring Time	Fine:1.2s; Tracking:0.7s Fine:0.7s; Tracking:0.7s			
Measuring System	basic frequency: 60MHz			
Atmospheric	Manual Input; Auto Correction Auto Sensing;			
Correction	Auto Correction Auto Correction		Auto Correction	



Atmospheric Refraction & Earth Curvature Correction	Manual input, Auto correction, K=0.14/0.20 se	electable	
Reflection Prism Correction	Manual input, Auto correction		
vial			
Plate vial	30" / 2 mm		
Circular vial	10' / 2 mm		
vertical compensato	or		
System	Liquid-electric detection/plate vial	Dual axis photoelectric detection	
Compensation Range	±3′	±4′	
Resolving Power	1"		
optical plummet			
Image	Erect		
Magnification	3×		
Focusing Range	0.3m~∝		
Field of View	5°		
display			
Туре	Graphical LCD, four lines		
communication			
Data Port	RS-232C RS-232C, mini USB, SD card		
battery			
Battery	Ni –H, rechargeable NB-28		
Voltage	6V(DC)		
Operation Time	5-6 hours	8-16 hours	
Operating Temperature	-20°C~+45°C		
Size & weight	160mm×150mm×340mm,5.4kg		

Precision

With reflector:

EDM Measuring Mode	Precision Standard Deviation	Time per Measurement
Fine	2mm+2ppm	<1.8s



Tracking	5mm+2ppm	<1.4s
IR reflecting sheet	5mm+2ppm	<1.2s

Without reflector:

EDM measuring	Accuracy Standard	Time per
program	deviation	measurement
Reflectorless fine	5mm+2×10 ⁻⁶	<1.2s
Reflectorless tracking	10mm+2x10 ⁻⁶	<0.8s

Beam interruptions, severe heat shimmer and moving objects blocking the beam path can result in deviations of the specified accuracy.

Range

With reflector

Atmospheric conditions	Standard prism	Reflecting sheet
5km	3000m	600m
20km	5000m	1200m

Without reflector

Atmoorphonic conditions	No reflector (white	No reflector
Atmospheric conditions	target) ※	(grey,0.18)
Object in strong sunlight,	RTS-820R: 180m	RTS-820R:100m
severe heat shimmer	RTS-820R ³ : 280m	RTS-820R3:150m
Object in shade, or sky	RTS-820R:200m	RTS-820R:120m
overcast	RTS-820R3:300m	RTS-820R3:180m

Kodak Grey Card is used with exposure meter for reflected light



14. ERROR CODE LIST

ERROR INFORMATION

ERROR CODE	DESCRIPTION	MEASURE
E001	Error in opening the	
	system parameter file	Format. If format is
E002	Error in opening files	invalidation, the instrument
E003	Error in initializing files	should be sent for repair.
E004	Error in writing files	
E005	Error in reading files	
E006	Error in deleting files	
E007	Error in checking	
	hardware	
E031	Angle error 1	
E032	Angle error 2	
E033	Angle error 3	Shut off the instrument and
E034	Vertical angle error 4	then reboot. If the error codes
E035	Horizontal angle error 5	appear again, the instrument
E036	Horizontal angle error 6	should be sent for repair.
E037	Vertical angle error 7	
E038	Angle error 8	
E33	Problem with EDM	Sent for repair.

15. SAFETY GUIDE

15.1 INTEGRATED DISTANCE METER (VISIBLE LASER)

Warning

The total station is equipped with an EDM of a laser grade of 3R/IIIa. It is verified by the following labels.

On the vertical tangent screw sticks an indication label "CLASS III LASER PRODUCT". A similar label is sticked on the opposite side.

This product is classified as Class 3R laser product, which accords to the following standards.

IEC60825-1:2001 "SAFETY OF LASER PRODUCTS".

Class 3R/III a laser product: It is harmful to observe laser beam continuously. User should avoid sighting the laser at the eyes. It can reach 5 times the emitting limit of Class2/II with a wavelength of 400mm-700mm.

Warning

Continuously looking straight at the laser beam is harmful.

Prevention

Do not stare at the laser beam, or point the laser beam to others' eyes. Reflected laser beam is a valid measurement to the instrument.

Warning

When the laser beam emits on prism, mirror, metal surface, window, etc., it is dangerous to look straight at the reflex.

Prevention

Do not stare at the object which reflects the laser beam. When the laser is switched on (under EDM mode), do not look at it on the optical path or near the prism. It is only allowed to observe the prism with the telescope of total station.

Warning

Improper operation on laser instrument of Class 3R will bring dangers.

Prevention

To avoid to be harmed, each user is required to take safety precautions, and take everything under control within the distance that would incur dangers (according to IEC60825-1:2001).

The following shows the explanation related to the key sections of the Standard.

Laser instrument of Class 3R is applicable outdoors and in construction field (measurement, defining lines, leveling).

- a) Only those persons who are trained with related course and authenticated are allowed to install, adjust, and operate this kind of laser instrument.
- b) Stand related warning symbols in the scale of use.



- c) Prevent any person to look straight at or use optical instrument to observe the laser beam.
- d) To prevent the harm caused by laser, block the laser beam at the end of the working route. When the laser beam exceeds the limit area (harmful distance*) and when there are motivating persons, stopping the laser beam is a must.
- e) The optical path of the laser should be set higher or lower than the line of sight.
- f) When the laser instrument is not in use, take care of it properly. The person who is not authenticated is not allowed to use.
- g) Prevent the laser beam from irradiating plane mirror, metal surface, window, etc., especially beware of the surface of plane mirror and concave mirror.
 - * Harmful distance means the maximum distance between the start point and the point which the laser is weakened to a degree that doesn't harm people.

The internal EDM instrument equipped with a Class 3R/III a Laser has a harmful distance of 1000m (3300ft). Beyond this distance, the laser intensity is weakened to Class I (Looking straight at the laser beam causes no harm to the eyes.)

15.2 LASER PLUMMET

The laser plummet built into the product produces a visible red laser beam which emerges from the bottom of the product. The product is a Class 2/IILaser Product.

Class 2 Laser Product is in accordance with:

IEC 60825-1:1993 "Safety of Laser Products"

EN 60825-1:1994 + A II:1996: "Safety of Laser Products".

Class II Laser Product is in accordance with:

FD121CFR ch.1\$ 1040:1998 (U.S. Health and Human Services Secretary, Federal rules code)

Class 2 Laser Products:

Do not stare into the beam or direct it unnecessarily at other persons. Eye protection is normally afforded by aversion responses including the blink reflex.



16. ACCESSORIES

item	quantity
carrying case	1
total station main body	1
battery	2
charger	1
plummet	1
correcting pin	2
fur brush	1
screw driver	1
hexagon wrench	2
cloth	1
dryer	1
operating manual	1
warrenty certificate	1
rain cover	1
software CD	1



【APPENDIX-A】 DESIGN ROAD LINE DATA

1. RAW DATA

The format of data transmitted from total station to the PC is as follows:

RUIDE FORMAT: Take RTS item as example

Data Transferred to PC	Explanation
CO,Ruide Raw data	The type of transmitted data
CO,RTS	File name
CO,Description:	JOB description
CO,Client:	
CO,Comments:	
CO,Downloaded 2007-03-02 22:40:59	Download date and time
CO,Software: Pre-install version:07.03.02	Software version number
CO,Instrument: Ruide RTS-820 S15101	Serial number of instrument
CO,Dist Units: Metres	Distance unit
CO,Angle Units: DDDMMSS	Angle unit
CO,Zero azimuth: North	AZ Zero azimuth
CO,VA: Zenith	VA Zero azimuth
CO,Coord Order: NEZ	Coordinate order
CO,HA Raw data: HA zero to BS	НА
CO, Projection correction: OFF	Projection correction
CO,C&R correction: ON	C&R correction
CO,Tilt Correction: OFF	Tilt correction
CO,RTS < JOB> Created 2007-03-02 22:37:25	JOB creating time
MP,1,,10.000,10.000,1.000,VM	Input coordinate manually,
MP,5,,50.000,50.000,5.000,MP	the sequence is: pointID,
	N/E, E/N, Z, code
CO,Temp:20.0 C Press:1013.2 hPa Prism:-30mm	Temp, Press, Prism constant,
2007.03.02 22:38:26	Date, Time
ST,1,,5,,1.600,45.0000,0.0000	Station data, the sequence
	is: Station pointID, Backsight
	pointID, height of instrument,
	azimuth(AZ), horizontal angle
	(HA)
F1,5,1.800,1.999,176.5958,99.2715, 23:26:28	Result of backsight point F1
	orientation, the sequence is:
	pointID, target height, slope
	distance, horizontal angle,
	vertical angle, time



SS,2,1.800,1.088,359.5959,62.4302, 22:38:45,MA	Target point measurement data, the sequence is: PointID, target height, slope
MP,99,,20.000,3.000,6.000,	distance, HA, VA, code
CO,Pt:100 SO deltas N: E: Z:-3.131	
SO,,,1.800,1.089,5.0432,84.5528, 22:40:28,	Data of stake-out, the sequence is: , , , , target height, slope distance, HA, VA, time

2. COORDINATE DATA

The format of uploaded/downloaded coordinate data is determined by user's setting. For example: the coordinate format is set as:

PointID, E, N, Z, Code 101,994.890,1000.964,100.113,RUIDE 102,993.936,1007.799,100.800,STN 103,998.515,1009.639,100.426,STN 104,1002.068,1002.568,100.342,STN 1001,1004.729,997.649,100.1153,PT 1002,1003.702,990.838,100.799,PT 1003,7911.990,990.358,100.403,PT 1004,997.311,998.236,100.354,PT

3. CODE LIST

The code list which is put in the code store, should be guaranteed that every line has one code which includes serial number and code, and every line is ended by carriage returns. The format of code list is:

Serial number (quick code number), code

When there is no definition of code, the code is default as the content of serial number. In quick code function, one can transfer code by entering serial number.

For example:

- 1, VEG
- 2, BDY
- 3, CL
- 4, ROAD

RUIDE

- 5, ROAD
- 6, PATH
- 7, DRAIN
- 8, CONTROL
- 9, DRAIN
- 10, UTILITY
- 11, UTILITY

4. HORIZONTAL LINE

The horizontal line is transmitted from computer to instrument through line element, including initial definition. It should be included in initial definition the number of the start stake and coordinate of this point. The line elements include point, straight, arc, and transition curve.

Each recorded format is:

(KEYWORD) nnn, nnn [, nnn]

Here:

START POINT stake number, E, N
STRAIGHT azimuth, distance
ARC radius, arc length
SPIRAL radius, length
PT E, N[, A1, A2]

(A1, A2: LENGTH)

For example1:

START 1000.000, 1050.000, 1100.000 STRAIGHT 25.0000, 48.420 SPIRAL 20.000, 20.000 ARC 20.000, 23.141 SPIRAL 20.000, 20.000 STRAIGHT 148.300, 54.679

Example 2:

START 1000.000, 1050.000, 1100.000 PT 1750.000, 1300.000, 100.000, 80.800 PT 1400.000, 1750.000, 200.000 PT 1800.000, 2000.000

RUIDE

5. VERTICAL CURVE

Input vertical curve data from computer through typical point and stake number, the vertical curve data should include the height, curve length, and the curve length of start point and terminal point is zero.

Data format is:

Stake number, height, length

For example:

1000.000, 50.000, 0.000

1300.000, 70.000, 300.000

1800.000, 70.000, 300.000

2300.000, 90.000, 0.000



【APPENDIX-B】 CALCULATE ROAD ALIGNMENT

The road alignment stake-out program can stake out the alignment elements including straight, arc and transition curve.

NOTE:

- 1) Road alignment data can be uploaded from computer or can be entered manually.
- 2) Road alignment data is managed by chainage.

1. ROAD ALIGNMENT ELEMENTS


There are two ways to enter the alignment elements:

- 1) Download from PC.
- 2) Manually entered on the RTS-850(R) series.

How to enter the alignment data is explained below:

Alignment Element	Parameter
Straight	Bearing, Distance
Transition Curve	Radius, Length of Transition Curve
Arc	Radius, Length of Arc
PT	N, E, radius, A1, A2

Note: When downloading from computer or selecting PT option, you do not have to calculate the Parameter.



Pt	North	East	Radius	Transition curve	A1 .	Transition	curve
A2							
	(N)	(E)	(R)				
BP	1100.000	1050.000					
IP1	1300.000	1750.000	100.000	80.000	80.000)	
IP2	1750.000	1400.000	200.000	0.000	0.000		
EP	2000.000	1800.000					



Example:

To enter the following data select DEF AL of ROADS in PROG menu:

Stake number	0
Ν	1100.000
E	1050.000

Press [ENT] and then press [F4] (PT), Enter the following data:

N	1300.000
E	1750.000
R	100.000
A1	80.000
A2	80.000

Enter the following data in the above way:

N	1750.000
Е	1400.000
R	200.000
A1	0.000
A2	0.000
Ν	2000.000
E	1800.000
R	0.000
A1	0.000
Δ2	0.000

The format of the data above transmitted to computer is as follows:

START 0.000, 1050.000, 1100.000 CRLF
PT 1750.000, 1300.000, 100.000, 80.000, 80.000 CRLF
PT 1400.000, 1750.000, 200.000, 0.000, 0.000 CRLF
PT 1800.000, 1800.000, 2000.000 CRLF

2. CALCULATION ROAD ALIGNMENT ELEMENTS (1)Calculation of the length of transition curve

$$L_{1.2} = \frac{A_{1.2}^2}{R}$$
 $L_{1.2}$: Length of clothoid

 $A_{1,2}$: Parameter of clothoid

R: Radius



$$L_1 = \frac{A_1^2}{R} = \frac{80^2}{100} = 64 \text{ m}$$

$$L_2 = \frac{A_2^2}{R} = \frac{80^2}{100} = 64 \text{ m}$$

(2) Calculation of Deflection Angle

$$\tau = \frac{L^2}{2A^2}$$

$$\tau_1 = \frac{64^2}{2 \cdot 80^2} = 0.32 \text{ rad}$$
 \Rightarrow deg \Rightarrow 0.32 $\frac{180}{\pi}$ =18°20′06″

$$\therefore \quad \tau_1 = -\tau_2$$

(3)Calculation of transition coordinates

$$N = A \cdot \sqrt{2\tau} \left(1 - \frac{\tau^2}{10} + \frac{\tau^4}{216} - \frac{\tau^6}{9360} \dots \right)$$
$$E = A \cdot \sqrt{2\tau} \left(\frac{\tau}{3} - \frac{\tau^3}{42} + \frac{\tau^5}{1320} - \frac{\tau^7}{7560} \dots \right)$$

$$N = 80 \cdot \sqrt{2 \cdot 0.32} \left(1 - \frac{(0.32)^2}{10} + \frac{(0.32)^4}{216} - \frac{(0.32)^6}{9360} \dots\right)$$

$$= 64\left(1 - \frac{0.01024}{10} + \frac{0.01048576}{216} - \frac{0.0010734148}{9360}\right)$$

$$= 64\left(1 - 0.010240.000048550.0000000\right)$$

$$= 64 * 0.98981$$

$$= 63.348$$

Similarly, the value of E is:

$$E = 80 \cdot \sqrt{2 \cdot 0.32} \left(\frac{0.32}{3} - \frac{(0.32)^3}{42} + \frac{(0.32)^5}{1320} - \frac{(0.32)^7}{7560} \dots \right)$$
$$= 64(0.10666667 - 0.00078019 + 0.0000025 - 0)$$
$$= 6.777$$

This example is symmetry spiral transition. N1=N2, E1=E2

(4)Calculation of shift value ΔR



$$\Delta R = E - R(1 - \cos \tau)$$

$$\Delta R = 6.777 - 100(1 - \cos 18^{\circ} 20'06'')$$
= 1.700

Symmetry spiral transition $\Delta R_1 = \Delta R_2$

(5) Calculation of Spiral Transition coordinates

$$N_m = N - R \sin \tau = 63.348 - 100 \sin 18^{\circ} 20'06'' = 31.891$$

Symmetry spiral transition $N_{m1} = N_{m2}$

(6) Calculation of Tangent Distance

$$D_{1} = R \tan(\frac{LA}{2}) + \Delta R_{2} \csc(LA) - \Delta R_{1} \cot(LA) + N_{m1}$$

$$LA = + 111^{\circ}55'47'', \qquad c \circ \&c = \frac{1}{\sin} \quad , \qquad \cot = \frac{1}{\tan}$$

$$D_{1} = 100 * \tan(111^{\circ}55'47''/2) + 1.7(1 / \sin111^{\circ}55'47'')$$

$$-1.7(1 / \tan 111^{\circ}55'47'') + 31.891$$

$$= 148.06015 + 1.8326 + 0.6844 + 31.891$$

$$= 182.468$$

$$D_{1} = D_{2}$$

(7)Calculation of the coordinate KA1

$$N_{KAI} = N_{IP1} - D_1 \cdot \text{co} \mathcal{U}_1$$

$$E_{KAI} = E_{IP1} - D_1 \cdot \text{sin} \mathcal{U}_1$$

Bearing from BP to IP1
$$\Rightarrow \alpha_1 = 74^{\circ}03'16.6''$$

$$N_{\text{KAI}} = 1300 - 182.468 * \cos 74^{\circ}03'16.6'' = 1249.872 \text{ m}$$

$$E_{\text{KAI}} = 1750 - 182.468 * \sin 74^{\circ}03'16.6'' = 1574.553 \text{ m}$$



(8) Calculation of Arc Length

$$L = R(LA - \tau_1 + \tau_2)$$
= $R(111^{\circ}55'47''-2 * 18^{\circ}20'06'')$
= $100(75^{\circ}15'35'' \frac{\pi}{180'})$
= 131.353 m

(9)Calculation of the coordinate KA2

$$N_{KA2} = N_{IP1} - D_2 \cdot c \circ \mathcal{U}_2$$

$$E_{KA2} = E_{IP1} - D_2 \cdot \sin \alpha_2$$

Bearing from IP1 to IP2
$$\Rightarrow \alpha_2 = 322^{\circ}07'30.1''$$

$$N_{KA2} = 1300 - (-182.468) \cdot \cos 322^{\circ}07'30.1'' = 1444.032 \text{ m}$$

$$E_{KA2} = 1750 - (-182.468) * \sin 322^{\circ}07'30.1'' = 1637.976 m$$

(10)Calculation of coordinates BC, EC which is ARC (IP1,IP2,EP)

Arc length
$$CL = R \cdot IA$$

 $IA = 95^{\circ}52'11''$

then

$$CL=200 * 95°52'11"* \frac{\pi}{180°} =334.648 \text{ m}$$

Tangent length

$$TL = R \cdot \tan(\frac{IA}{2}) = 200 * \tan(95^{\circ}52'11''/2) = 221.615 \text{ m}$$

Each coordinates are computed:

$$N_{BC} = N_{IP2} - TL \cdot \cos \alpha_2$$

$$E_{BC} = E_{IP2} - TL \cdot \sin \alpha_2$$

$$N_{EC} = N_{IP2} - TL \cdot \cos \alpha_3$$

$$E_{EC} = E_{IP2} - TL \cdot \sin \alpha_3$$



here:


$$\alpha_2$$
 (Bearing from IP1 to IP2) = 322°07′30.1″

$$\alpha_3$$
 (Bearing from IP2 to EP) = 57°59′40.6″

$$N_{BC} = 1750 - 221.615 * \cos 322°07′30.1″ = 1575.068 m$$
 $E_{BC} = 1400 - 221.615 * \sin 322°07′30.1″ = 1536.058 m$ $N_{EC} = 1750 - (-221.615) * \cos 57°59′40.6″ = 1867.456 m$

$$E_{EC}$$
 = 1400 –(-221.615) * sin57°59′40.6″=1587.929 m

The calculated results display as below:



The coordinates and the distance are calculated as below:

(1)Compute the length of straight line

Straight line

BP·KA1=
$$\sqrt{(1249.872-1100.000)^2 + (1574.553-1050)^2} = 545.543 \text{ m}$$

straight line KA2·BC
= $\sqrt{(1575.068-1444.032)^2 + (1536.058-1637.976)^2} = 166.005 \text{ m}$

RUIDE

straight line

$$\text{EC-EP} = \sqrt{(2000 - 1867.456)^2 + (1800 - 1587.929)^2} = 250.084 \text{ m}$$

Start point coordinate (BP)

N 1100.000 m E 1050.000 m

Straight line (between BP and KA1)

Bearing 74°03′16.6″ Distance 545.543 m

Transition clothoid (between KA1 and KE1)

Radius -100 m ("-"sign is turn left curve toward the end point)

Length 64 m

ARC (between KE1 and KE2)

Radius -100 m ("-" sign is turn left curve toward the end point)

Length 131.354 m

Transition (Between KE2 and KA2)

Radius -100 m ("-" sign is turn left curve toward the end point)

Length 64 m

Straight line (between KA2 and BC)

Bearing 322°07′30.1″ Distance 166.004 m Arc (between BC and EC)

Radius 200 (without sign is turn right curve toward the end point)

Length 334.648 m

Straight line (between EC and EP)

Bearing 57°59′40.6″ Distance 250.084 m